

PRIMARY CORNER DESCRIPTION Cor. No. 18 HES 143

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

HES No. 143 by Frank D. Maxwell, surveyor (FS), under special instructions dated April 27, 1914 - Surveyed June 1914- DCSO records Vol. 28 Page(s) 12022)

Cor. No. 18, identical with Cor. H/3, a hemlock tree 20" dia. mkd. and witnessed as described by the listing surveyor, I mark tree 18 HES 143 on SE. face, with a blaze on the NE. and SW, faces, for cor. 18; from which

A hemlock, 20" dia., bears N.74°00'W., 16 lks.
 A fir, 12" dia., bears N.5°30'W., 50½ lks.
 both trees blazed and scribed 18 HES 143 R T.

Pits & mound impracticable at this and all other cors.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & V. Perron - 12/15/1969 - C.S. File 54/82-96

Found - Stump of Orig. 20", now 21" Hemlock corner tree, scribed "18 HES 143" on SE and "H 3" on SW.
 Orig. BTs would fall in roadway.
 We remove corner stump & in its place set brass cap with steel fence post alongside. COUNTY SURVEYORS T29S R1E OFFICE 1969 COR #18<HES 143

New BTs- 17" D.Fir N.25°W., 74.3 ft. mkd: "18 HES 143 CS BT"
 This corner lies on E edge of USFS access road near intersection.



Fd. BC & 1 BT by Farr, USFS - July 1975 - M56-26

Leonard Herzstein, USFS & Deputy Co. Surveyor - Witnesses: Jim Landrum & Thm. Wolford - April 8, 1981 - C.S. 61/19-33

Found - 1" IP firmly set buried 2" under ground with brass cap properly marked. (1969 County) Steel fence post set next to monument to the south.
 Orig. corner tree, 20" Hemlock root crown alongside with fragmentary scribe marks visible on previously opened blaze.
 21" D.Fir, N.25°W., 74.3 ft. with healed blaze. 1969

New BT - A 11" D.Fir, N.47½°E., 8.5 ft. marked "18 HES 143 CS BT" on a double blaze.