

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 979140

PRIMARY CORNER DESCRIPTION Cor. No. 14 Tract B; HES 179

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

HES No. 179 by Frederick W. Rase, surveyor, under special instructions dated Dec. 17, 1915 - Surveyed September 1916 - DCSO records Vol. 28 Page(s) 12049-50

Cor. No. 14, identical with cor. No. 5 of listing survey, which I destroy and in its place
Set a granite stone, 28x8x8", 18" in the ground, over a stone marked with a cross for cor. No. 14 of this survey, marked 14 HES 179 on side facing the claim; from which
 A yew, 8" dia., bears N.17°45'E., 31 lks., mkd X 14 HES 179 BT.
 A fir, 14" dia., bears S.1°30'W., 22 lks., marked X 14 HES 179 BT.
Raise a mound of stone, 3 ft. base, 2 ft. high, 3½ ft. within the claim.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - 12/1969 - C.S. File 54/82-90

Reported as not found.
Probably destroyed by road - & river course change

Gordon H. Long, USFS - For: USFS - Aug 1976/Jan 1978 - M65-77 & C.S. File 58/162-5 A-G

Found - All original evidence of this corner was destroyed when the South Umpqua Road was constructed. The proportioned corner point, which falls in the road, was monumented with a brass cap monument and new bearing trees were blazed and scribed.
Set - 1"x24" galv. pipe with 2½" brass cap marked:
 "T29S R1E HES 179 COR. 14 RPLS 1017 1976" Brass cap is 0.5' below road surface, from which
 A 36" Cedar N.60°30'E. 41.3' scribed "14 HES 179 BT"
 A 48" D.Fir S.46°W., 206.8' scribed "14 HES 179 BT"

Fd. Ok, 9/20/1994 by L. Herzstein, C.S. File 63/158-I
