

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec Cor for 19 & 30 only (West bdy)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6227)

Set an Iron post 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 19 and 30, with brass cap mkd:

T29S
S19
S30
R2W

1917

from which

A Fir 36" dia., bears N.53°15'E., 22 lks. dist. mkd. T29S R2W S19 BT.

A Fir 30" dia., bears S.54°E., 32 lks. dist. mkd. T29S R2W S30 BT.

Fd. OK, July 20, 1973 by DCSO, V.Tracy - C.S. File 56/34-19

BLM resurvey by James J. Carlson, Cadastral Surveyor, under Group #892, surveyed June/July 1976 - (DCSO records Vol. 39 Page(s) 15836-37)

The cor. of secs. 19 and 30 only, on the W. bdy. of T29S R2W, monumented with an iron post, 2" dia., firmly set, projecting 8" above ground and mkd. as in 1917

from which the remains of the original bearing trees:

A sawed Fir stump 26" dia., bears N.53¼°E., 22 lks. dist., with healed blaze.

A root hole bears S.54°E., 32 lks. dist.

and a new bearing tree

A Fir 5" dia., bears N.11¼°E., 148 lks. dist. mkd. X BT.

Mark Smalley - For: Roseburg Resources Co. - Oct. 1999 - M 134-8

Found - Brass cap on iron pipe.

11" Fir N.11¼°E., 97.7 ft. healed.

26" Fir stump N.53¼°E., 14.5 ft. orig.

New BT - 9" Fir N.44°E., 29.4 ft. "S 19 BT"