

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 18 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6229)

-----

Set an iron post 3 ft. long, 1" dia., 26" in the ground for 1/4 cor. of sec. 18 only, with brass cap marked:

1/4  
S18  
1917

from which

A Fir 20" dia., bears N.31°15'E., 65 lks. dist. mkd. 1/4 S18 BT.

A Fir 20" dia., bears S.84°E., 46 lks. dist. mkd. 1/4 S18 BT

---

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Dec. 1962 - C.S. File 52/126-84

-----

Found brass cap at corner and both BTs as recorded. NE. BT, now snag, shows scribing. SE. BT, now down.  
New BT - 20" Fir bears S.24°E., 20.2 ft. scribed 1/4 S18 CS BT.  
No other BTs. scribed.

---

Tony Hostetter - For: Seneca Jones Tbr Co - 4/2006 - M150-38

-----

Found - 1917 brass cap as described by Byron in 1962 (C.S. File 52/126)

Fir BT @ N.31°15'E., is now a very rotten stump.  
24" Fir stump, face evident, BLM tag, bears S.24°E., 20.2 ft. (Note: This is the same BT as described as being S.50°E., 19 lks from the SE corner of sec. 12)

New BTs- 8" Fir, scribed "S18 1/4 BT" bears N.49°E., 19.2 ft. to spike.

10" Fir, scribed "S18 1/4 BT" bears N.17°W., 18.7 ft. to spike.