

PRIMARY CORNER DESCRIPTION Sec Cor for 1 & 12 only, T29-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6323)

-----  
Set Cedar post for cor. to secs. 1, 6, 7 and 12, from which  
A Laurel 15" dia., bears N.8°E., 45 lks.  
A Fir 18" dia., bears S.72°E., 24 lks.  
A Fir 30" dia., bears S.20°W., 18 lks.  
A Fir 28" dia., bears N.48°W., 50 lks.

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6230)

-----  
Intersect the old cor. of secs. 1, 6, 7 and 12, which is a badly decayed post, marked and witnessed as described by the surveyor general, with the exception that the NE. bearing tree has been destroyed. I change this cor. to refer to secs. 1 and 12 only and perpetuate it as follows: alongside the old cor.  
Set a basalt stone 16x10x5 ins., 12" in the ground marked with 5 notches on S. and 1 notch on N. edge; from which  
A Fir 36" dia., bears S.20°W., 18 lks. dist. mkd. T29S R3W S12 BT. (Old BT)  
A Fir 34" dia., bears N.48°W., 50 lks. dist. mkd. T29S R3W S1 BT. (Old BT)

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Dec. 1962 - C.S. File 52/126-87

-----  
Found stone at corner and both BTs as recorded. SW. BT, now stump. NW. BT, shows scribing.  
Set Brass cap alongside cor. stone & mkd:  
County Surveyors Office  
S 1 | T29S  
R3W S 12 | R2W  
1962  
New BTs- 20" Cedar bears S.81°W., 38.3 ft. mkd. S12 T29S R3W CS BT.  
7" Cedar bears N.22°W., 29.2 ft. mkd. S1 T29S R3W CS BT.

Fd. and used in BLM resurvey by James J. Carlson, Cadastral Surveyor, under Group #892, surveyed June/July 1976 - (DCSO records Vol. 39 Page(s) 15841)

Fd. Ok by Tony Hostetter 4/2006 - M150-38