

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6271)

Set an iron post, 3 ft. long, 1 in. dia., 26 ins. in the ground, for 1/4 sec. cor., with brass cap marked $\frac{1}{4}$
S32 | S33
1917

from which
A Fir 12" dia., bears S.42°15'E., 33 lks. dist. mkd. $\frac{1}{4}$ S33 BT.
A Fir 24" dia., bears N.87°30'W., 69 lks. dist. mkd. $\frac{1}{4}$ S32 BT.

Douglas County Surveyors Office - Gary L. Langlitz, Deputy - M. Lenora Ladig, crew - Dec. 24, 1975 - C.S. File 57/39-46

Found - 1917 GLO brass cap, firmly set and properly mkd.
An Orig. 12" D.Fir now a 14" snag, with a good scar, bears S.42 $\frac{1}{4}$ °E., 21.8 ft.
An Orig. 24" now 29" D.Fir alive and well healed, bears N.87 $\frac{1}{2}$ °W., 44.2 ft. (Rec. N.87 $\frac{1}{2}$ °W., 45.5 ft.)
New BT - 20" D.Fir bears N.18°E., 46.0 ft. scribed " $\frac{1}{4}$ S33 CS BT" in a double blaze.