

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6272)

Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 28, 29, 32 and 33, with brass cap marked

T29S R2W
S29|S28
S32|S33
1917

from which

- A Fir 18" dia., bears N.66°15'E., 39 lks. dist. mkd. T29S R2W S28 BT.
- A Cedar 14" dia., bears S.79°E., 38 lks. dist. mkd. T29S R2W S33 BT.
- A Fir 24" dia., bears S.45°30'W., 104 lks. dist. mkd. T29S R2W S32 BT.
- A Fir 15" dia., bears N.6°W., 45 lks. dist. mkd. T29S R2W S29 BT.

Douglas Co. Surveyors Office - A. Victor Cangie; Mike Tompkins, crew - Nov. 16, 1976 - C.S. File 56/26-14

Found - 2" I.P. firmly set with brass cap stamped properly. This monument is in good condition.
An 18" now 27" orig. Fir, bears N.66¼°E., 25.7 ft. Healthy and shows good scar.
An orig. 14" now 20" Cedar bears s.79°E., 25.1 ft. Healthy and shows good scar.
An orig. 24" now 38" Fir, bears S.45½°W., 68.6 ft. Healthy and shows good scar.
An 18" Fir windfall that fits reasonably well for bearing and distance for the orig. NW. BT but we find no evidence to verify it as a BT.
New BT - A 10" W.Fir bears N.9°W., 44.0 ft. mkd. "T29S R2W S29 CS BT" in a double blaze.
We stamp "CS 1976" on found brass cap.