

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 15 Page(s) 6200-01) (Duplicate pgs. 6824-25)

-----

Set a porphyry stone 18x10x8 ins., 12" in the ground for cor. of secs. 4, 5, 32 and 33, marked with 4 notches on E. and 2 notches on W. edge, from which

- A Maple 15" dia., bears N.54°E., 37 lks. dist. mkd. T29S R2W S32 BT.
- A Fir 30" dia., bears S.29°E., 6 lks. dist. mkd. T30S R2W S4 BT.
- A Cedar 12" dia., bears S.22½°W., 21 lks. dist. mkd. T30S R2W S5 BT.
- A Fir 12" dia., bears N.53½°W., 23 lks. dist. mkd. T29S R2W S32 BT.

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6219)

-----

Intersect the cor. of secs. 4, 5, 32 and 33, which is a porphyry stone, firmly set, marked and witnessed as described by the surveyor general. I change this cor. to refer to secs. 4 and 5, T30S R2W only by destroying all marks referring to secs. 32 and 33. From Cor.

- A Fir 30" dia., bears S.29°E., 6 lks. dist., mkd. T30S R2W S4 BT. (Old BT)
- A Cedar 12" dia., bears S.22°30'W., 21 lks. dist. mkd. T30S R2W S5 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Nov. 21, 1968 - C.S. File 54/73-45

-----

Found - No trace of stone at section corner.  
 30" now 38" D.Fir S.29°E., 4.0 ft., shows good scar.  
 12" Cedar now stob, S.22½°W., 13.9 ft., opened for scribe.

Set Brass cap at cor. mkd: County Surveyors Office

T 29 S	
T 30 S	R2W ¼
	1968
	S 5   S 4

New BTs- 14" Hemlock S.64°W., 39.7 ft. mkd. T30S R2W S5 CSBT  
 8" Fir N.34°W., 10.0 ft. mkd. T29S R2W S33 CS BT.

This corner lies 62.7 ft. East of Secs. 32 & 33, T29-2

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 301100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5 only, T30-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2232, Surveyed Oct. 2008/April 2009 - (DCSO records Vol. 57 Page(s) 22647)

-----  
The cor. of secs. 4 and 5 only, on the N. bdy. of the Tp., perpetuated by the Douglas County Surveyor's Office in 1968, monumented with an iron post, 1½" dia. firmly set, projecting 15" above ground, with brass (properly) mkd. from which the remaining orig. bearing tree

A fir, 43" dia., bears S.29°E., 4.0 ft., with a healed blaze.

and BTs mkd. by the Douglas County Surveyor's Office in 1968

A hemlock, 19" dia., bears S.64½°W., 40.0 ft., with a healed blaze.

A fir, 11" dia., bears N.35°W., 9.8 ft., with a healed blaze.

Corner is located at the base of the westerly shoulder of a gravel road.

Ron Quimby - Crew: N. Fromdahl & R Heichel- 9/2018 - C.S. File 65/102-3

-----  
Found - DCSO brass cap (properly marked)  
44" D.Fir S.29°E., 4.0' good scar (Orig. BT)  
20" Hemlock S.64°W., 39.7 ft. good scar.  
10" Fir snag N.34°W., 10.0 ft. good scar.  
Brass cap S32|S33 only West 61.8 ft. (rec. 62.7)  
New - 10" Fir S.45°W., 40.0 ft scribed T30S R2W S5 BT  
Note - Corner is at toe of road fill.  
Compass decl. 15½°E.