

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6278)

-----  
Set an iron post, 3 ft. long, 1 in. dia., 26 ins. in the ground, for 1/4 sec. cor., with brass cap marked

      S 9  
      -----  
1/4 S16  
      1917

from which

    A Hemlock 12" dia., bears S.40°15'W., 50 lks. dist. mkd.  
      1/4 S16 BT.

    A Hemlock 16" dia., bears N.41°45'W., 43 lks. dist. mkd.  
      1/4 S9 BT.

Note: 1961 DCSO corner reference notes, C.S. 52/89, are confusing, don't appear to fit and are not typed.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & J. Brady, crew - Oct. 13, 1967 - C.S. File 54/58-4

-----  
Found - 1917 GL0 brass cap, properly mkd. but out of ground.  
          RESET brass cap at 1/4 cor. which falls at edge of road.

          12" Hemlock now stump, S.40°W., 33.0 ft. scribe visible "1/4 S16 BT".

          No trace of NW. BT, falls in road right-of-way.

New BTs- 18" Hemlock S.24°W., 48.0 ft. mkd. 1/4 S16 CS BT.

          24" D.Fir N.84°W., 67.8 ft. mkd. 1/4 S9 CS BT.