

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 4 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6237)

Set an iron post 3 ft. long, 1" dia., 26" in the ground, for 1/4 cor. of sec. 4 only, with brass cap mkd.

1/4 S4
1917

from which

A Fir 44" dia., bears S.86°15'E., 71 lks. dist., mkd. 1/4 S4 BT.

A Fir 40" dia., bears S.14°W., 38 lks. dist., mkd. 1/4 S4 BT.

Douglas County Surveyors Office - James W. Byron, Surveyor
John Powell and crew - C.S. File 54/26-1A - July 1971

Corner searched for, not found.

Found, probable SE BT now stump. Opened stump with saw to find burnt face. Found 1 mark that may be a scribe mark but not sure of it. To where cor. should lie, hits calls of about 12 chains and 5 chains. This cor. should have 1917 brass cap which now seems to fall in a spot cleared and leveled for a possible stock pile site.