

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 376700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 33 only, T28-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William N. Gibb, Deputy Surveyor, under Contract #783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5432)

Set Fir post 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. marked ¼ S33 on N. face, and dig pits 18x18x12 ins., E. and W. of cor., and raise mound of earth, 3½ ft. base, 1½ ft. high, N. of cor., from which
A Fir 10" dia., bears N.23°W., 6 lks. dist. mkd. ¼ S33 BT.
No other tree fit to mark.

GL0 resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6237)

The ¼ cor. of sec. 33, which is a Fir post, firmly set, marked and witnessed as described by the surveyor general. I perpetuate this cor. as follows: alongside the old cor. Set a basalt stone 15x8x6 ins., 10" in the ground for ¼ sec. cor., marked ¼ on N. face; from which
A Fir 8" dia., bears N.38°30'E., 29 lks. dist. mkd. ¼ S33 BT (New BT)
A Fir 10" dia., bears N.23°W., 6 lks. dist. mkd. ¼ S33 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell, J. Heritage; V. Perron, crew - Oct. 26, 1970 - C.S. File 54/40-196

Found - Stone mkd. "¼" on N. face as called for.
Orig. BT, 10" now 22" Fir, alive, N.23°W., 4.0 ft. shows good scar.
No trace of 1917 orig. BT.
Set Brass cap at cor. mkd: County Surveyors Office
T28S R2W S 33
T29S
1970

Reset old stone alongside.
New BT - 7" W.Fir N.7°E., 55.1 ft. mkd. ¼ S33 CS BT.
Corner lies in shallow ravine, course South.
(The record dist. 258.1 ft., from this ¼ cor. to sec. cor. 3 & 4, T29-2, appears to be very close. We do not measure due to logging debris on line.)

continued next page

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 376700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec 33 only, T28-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Joseph M Mannix, Cadastral Surveyor and Justin V Haddon, Cadastral Surveyor under Group No. 2957, surveyed Oct/Nov. 2019 - (DCS0 records Vol. 59 Page(s) 23935)

The ¼ sec. cor. of sec. 33 only, T28S R2W perpetuated by Douglas County Surveyor's Office, in 1970; monumented with an iron post 1¼" dia. firmly set, projecting 11" above ground, with a brass cap (properly) mkd.

from which the bearing tree reported by Strickler in 1917

A fir, 32" dia., bears N.23°W., 4.0 ft., with a healed blaze. (Original)

and a bearing tree mkd. by Douglas County Surveyor's Office

A fir, 12" dia., bears N.5¾°E., 53.8 ft., with a healed blaze.

and a bearing tree mkd. by person(s) unknown

A fir, 35" dia., bears S.54¾°E., 21.8 ft., with a healed blaze.

Added to DCS0 records 3/30/2022

Brent Knapp - For: Umpqua Indian Forest Management, LLC - 9/2021 - M179-80

Found - Brass cap

35" Fir bears N.23°W., 4.0' (unmarked)

24" Fir bears N.7°E., 55.1' (unmarked)

Set - A metal post bears 5.0' east

A metal post bears 5.0' west