

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6253)

Set an iron post, 3 ft. long, 1 in. dia., 26 ins. in the ground, for 1/4 sec. cor., with brass cap marked

$\frac{1}{4} \frac{S26}{S35}$
1917

from which

A Maple 10" dia., bears N.53°30'E., 27 lks. dist. mkd. $\frac{1}{4}$ S26 BT.

A Maple 20" dia., bears S.60°E., 52 lks. dist. mkd. $\frac{1}{4}$ S35 BT.

Douglas County Surveyors Office - VRT & Crew - Nov. 1969 - C.S. File 54/96-12

Corner searched for, not found. Land cleared with cat. No O.B.Ts or brass cap found.