

PRIMARY CORNER DESCRIPTION Sec Cor for 24 & 25 only, T29-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6298)

Set a post cor. of secs. 19, 24, 25 and 30, from which
A Red Fir 10" dia., bears N.5°E., 45 lks. dist.
A Red Fir 8" dia., bears S.45°E., 17 lks. dist.
A Red Fir 6" dia., bears N.60°W., 15 lks. dist.
A Red Fir 8" dia., bears S.55°W., 15 lks. dist.

W.H. Byars, GLO surveyor, fd. above corner, under Contract #376, dated Jan. 22, 1881 (DCSO records, Vol. 15 Pgs. 6316-17)

A.R. Evans, Deputy Co. Surveyor - Wit: F.D. Smith; Harvey Potter; Ivan Taylor - May 1949 - M 1-31

Found rotted and burned stumps of NW and SW. BTs, scribe marks visible.
Set 1" G.I.P. with brass cap mkd. "Co. Surv. Off. T29S R4W Sec. Cor 24|25 R.E. 2741".
Nailed brass disk on 30" Fir mkd. Co. Surv. Off., Sec. Cor. 24 25 T29S R4W, set by Reg. Engr. No. 2741.
30" Fir bearing N.20°W., 14.2 ft. mkd. T29S R4W S24 CS BT.
24" Fir bearing S.40°E., 20.9 ft. mkd. T29S R4W S25 CS BT.
No trees in Sec. 25.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - Nov. 1962 - C.S. File 52/126-77

Found - Brass cap at cor. and both BTs as recorded by Evans, except NW. BT which is now gone.
New BT - 7" Red Fir N.14°00'W., 23.4 ft. scribed S24 CS BT.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13790-91)

The cor. of secs. 24 and 25 only, on the E. bdy. of T29S R4W, remonumented by Evans in 1949, and rehabilitated by Byron in 1962, monumented with an iron post, 1" dia., 6" above ground, firmly set, with brass cap mkd:

COUNTY SURVEYORS OFFICE
T 29 S R 4 W
24 | sec.
25 | cor.
RE 2741

from which the remains of the original SW. bearing tree;
(Cont. Next Page)

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 100308

PRIMARY CORNER DESCRIPTION Sec Cor for 24 & 25 only, T29-4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A rotted Fir stump 14" dia., bears S.76½°W., 15 lks. dist., with fragmentary scribe marks visible. (Record S.55°W.)
and bearing trees mkd. by Evans:
A Fir 25" dia., bears S.45°E., 31 lks. dist. with a partially healed blaze.
A down Fir 25" dia., bears N.70°W., 23 lks. dist. mkd. T29S R4W S24 CS BT on bark blaze.
and a bearing tree mkd. by Byron:
A Fir 7" dia., bears N.14 3/4°W., 35 lks. dist., with a partially healed double blaze.
and a new bearing tree:
A Fir 8" dia., bears S.57½°W., 48 lks. dist. mkd. T29S R4W S25 BT.
Add the marks BLM to the brass cap.

Cor. Fd. and tied in BLM survey by Roseberry and Jelley, Group #'s 255; 701; 938 - surveyed July 1967/Oct. 1977 - (DCSO records, Vol. 39 Pages 15860-61)

FD BC & BTs of record by N. Hibbs, 8/2016 - M172-46