

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6308)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Fir 18" dia., bears South 25 lks. A Maple 12" dia., bears N.63°W., 58 lks.</p>
<p>Fd. and used in GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6345)</p>
<p>BLM Resurvey by James E. Jelley and Lynn Roseberry Cadastral Surveyors under Group #554 - Surveyed May 1966/Oct. 1967 - (DCSO records Vol. 34 Page(s) 14043-44)</p> <p>-----</p> <p>Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd: T 29 S R 3 W ¼ S 9 S 16 1966</p> <p>from which A Cedar 7" dia., bears N.25°E., 15½ lks., mkd. ¼ S9 BT. A Fir 6" dia., bears S.4°E., 39 lks. mkd. ¼ S16 BT.</p>
<p>Fd. OK by R. Brown, May 2000 - M132-40</p>
<p>BLM resurvey by George M. Winter, Cadastral Surveyor under Group No. 2654, surveyed Oct./Nov. 2012 - (DCSO records Vol. 58 Page(s) 23029-30)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 9 and 16, monumented with an iron post, 2½" dia., firmly set, projecting 9" above ground, with brass cap (properly) mkd. from which remains of bearing trees mkd. by Jelley and Roseberry in 1966-67 A cedar, 16" dia., bears N.25°E., 10.2 ft., with a hollowed blaze. A decayed fir snag, 19" dia., bears S.4°E., 25.7 ft., with a healed blaze. and a new bearing tree A maple, 9" dia., bears S.11½°E., 22.8 ft., mkd. ¼ S16 BT. Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center. Corner is located 2 ft. W. and 7 ft. N. of fences extending E. and S.</p>