

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6302)

-----  
Set post cor. secs. 27, 28, 33 and 34, from which  
A Fir 10" dia., bears S.89°W., 53 lks. dist.  
A Fir 10" dia., bears N.89°W., 51 lks. dist.  
A Fir 15" dia., bears N.62°E., 73 lks. dist.  
A Fir 24" dia., bears S.70°E., 76 lks. dist.

GL0 survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6339)

-----  
Set new post, witness trees all standing. (As described above)

Ben B. Irving, Deputy Co. Surveyor - N.E. Richardson; Loren Weber - May 29, 1941 - C.S. File 16/55

-----  
Location identified from original BT:  
S.89°W., 51 lks. which I chop out and find scribe marks in excellent condition.  
N.89°W., 53 lks. standing and in good shape, remarked but not chopped out.  
N.62°E., 73 lks. standing and in good shape, remarked but not chopped out.  
Drove a 1¼" x 48" Iron pipe 40" in the ground for the corner and set a 6" x 6" x 48" Yewood post alongside. Blazed and scribed  
A Fir 24" dia., which bears S.6°E., 23 lks. for a new BT replacing the Orig. BT, S.70°E., 76 lks. which has been destroyed.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S.A. Bilow, crew - Feb. 19, 1959 - C.S. File 49/47-8

-----  
Found - Stump of orig. NE BT, I open & find gd. scribing "B"  
Orig. 15" now 36" Fir N.62°E., 48.2 ft., shows good bark scribing.  
Orig. 10" now 30" Fir S.89°W., 35.0 ft., previously opened, shows good scribing.  
24" Fir scribed by Irving, recorded S.6°E., 15.2 ft. should be South 9.5 ft.  
1¼" Iron pipe bears N.7°W., 5.7 ft.  
I find three original BTs, all check bearing and distance except the NW. and SW. BTs., which have distances reversed. I use orig. BTs to fix position of section corner.  
(Cont. Next Page)

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S R 3 W  
S 28 | S 27  
S 33 | S 34  
1959

New BTs- 15" R.Fir bears N.31°W., 29.0 ft. scribed T29S R3W  
S28 CS BT.  
12" R.Fir bears N.34°E., 17.5 ft. scribed T29S R3W  
S27 CS BT.  
17" R.Fir bears S.51°E., 45.2 ft. scribed T29S R3W  
CS BT.

BLM Resurvey by James E. Jelley and Lynn Roseberry Cadastral  
Surveyors under Group #554 - Surveyed May 1966/Oct. 1967 -  
(DCSO records Vol. 34 Page(s) 14037-38)

-----  
(Corner Report)

The Sec. cor. perpetuated and recorded by Irving in 1941,  
again perpetuated and recorded by Byron in 1959, monumented  
with an iron post, 1" dia., firmly set, extending 14" above  
ground, with 1959 brass cap

from which the remaining original bearing trees

A Fir 33" dia., bears N.63°E., 75½ lks. dist., with the  
original healed blaze and bark scribed T29S R3W 27 CS  
BT by Irving in 1941. (Rec. N.62°E., 73 lks.)

A Fir 27" dia., bears S.87½°W., 50 lks., with scribe marks  
33 visible on partially opened original blaze and bark  
scribed T29S R3W S33 CS by Irving in 1941. (Rec.  
S.89°W., 53 lks.)

A sawed Fir stump 30" dia., bears N.89½°W., 54 lks., with  
scribe marks BT visible on the remaining portion of  
opened blaze. (Rec. N.89°W., 51 lks.)

and a bearing tree mkd. by Irving in 1941

The root hole of an uprooted Fir, 23" dia., bears S.16°E.,  
14 lks. with CS & other illegible bark scribed visible.

and bearing trees mkd. by Byron in 1959

A Fir 15" dia., bears N.24½°E., 27 lks., with a healed  
double blaze.

A Fir 18" dia., bears S.53¼°E., 68 lks., with scribe marks  
BT visible on partially healed double blaze.

A Fir 16" dia., bears N.33°W., 43½ lks. with a healed blaze.

Ronald L. Rice, Ward NW - For: Seneca Jones Timber Co. -  
10/2004 - M 145-76

-----  
Found - 2½" County Surveyors brass cap dated 1959 with the  
following accessories;  
continued next page

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Fir bears N.63°E., 49.8' - healed face  
28" Fir bears N.24½°E., 17.8' - healed face  
27" Fir bears S.53¼°E., 44.8' - healed face  
24" Fir stump bears N.33°W., 28.7' - healed face  
New BT - 13" D.Fir bears S.77°W 5.2' - blazed, scribed "T29S  
R3W S33 BT"

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2804, surveyed Aug/Sept 2015 - (DCS0 records Vol. 58 Page 23423-5 & Plat T29-3 2017-1)

-----  
The cor. of secs. 27, 28, 33, & 34, perpetuated by Rice, in 2004, monumented with an iron post, 1¼" dia., firmly set, projecting 13" above ground, with brass cap (properly) mkd. from which the remains of the original BTs reported by Jelley and Roseberry in 1966-67

A fir, 38" dia., bears N.63°E., 49.8 ft., with a healed blaze and scribe marks T29S R3W CS visible on the bark.

A decayed fir stump, size indeterminate, bears S.87½°W., 33.0 ft., with no marks visible.

A root hole, bears N.89½°W., 35.6 ft., alongside of which is a fallen, decayed Or snag, 30" dia., with no marks visible.

and the remains of a BT mkd. by Irving, in 1941, and reported by Jelley and Roseberry

A root hole, bears S.16°E. 9.2 ft., alongside of which is an uprooted, decayed fir stump, 26" dia., with no marks visible.

and the remains of the BTs mkd. by Byron, in 1959, and reported by Jelley and Roseberry

A fir, 29" dia., bears N.24½°E., 17.8 ft., with a healed double blaze.

A fir, 28" dia., bears S.53¼°E., 44.9 ft., with a healed double blaze.

A decayed fir stump, 15" dia., bears N.33°W., 28.7 ft., with no marks visible.

and the BT mkd. by Rice

A fir, 14" dia., bears S.75¾°W., 5.2 ft., with a healed blaze.

and a new bearing tree

A fir, 9" dia., bears N.61°W., 45.6 ft., mkd. X BT. BT has a 2½"x¼" (Mag Nail) driven at the base on right side center  
NAD 1983 (2011)

Latitude 43°00'49.14"N. Longitude 123°03'33.87"W.