

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCS0 records Vol. 15 Page(s) 6303)

-----  
Marked a Fir 10" dia., for 1/4 sec. cor., from which  
A Fir 18" dia., bears N.40°W., 17 lks.  
A Fir 15" dia., bears N.40°E., 18 lks.

Fd. and used in GL0 survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCS0 records Vol. 15 Page(s) 6341)

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S.A. Bilow, crew - Feb. 19, 1959 - C.S. File 49/47-9

-----  
Found - Orig. 18" now 36" R.Fir, N.40°W., should be N.53°W.,  
I open and find good scribing "1/4S".  
Orig. 10" now 16" down Fir Corner tree, previously  
opened, shows good scribing "1/4S".  
Orig. NE. BT, shows good scar, I do not open.  
Set brass cap at corner tree mkd: County Surveyors Office  
T 29 S R 3 W  
1/4 S28 | S27  
1959

New BTs- Rescribe orig., N.32°E., 12.6 ft. 16" R.Fir "1/4 S27  
CS BT"  
38" Cedar bears N.39°W., 32.7 ft. scribed "1/4 S28 CS  
BT".

Survey by Bruce A. Shaner, PLS #430 - For: Longview Fibre Co.  
Aug. 10, 1979 - M 70-80

-----  
Found - 1959 County brass cap.  
36" D.Fir, orig. BT, stump bears N.53°W., 11.5 ft.  
16" D.Fir, orig. BT, blowdown, scribes visible,  
bears N.32°E., 12.6 ft.  
38" I.Cedar BT, scribes visible, bears N.39°W., 32.7  
ft.  
New BT - 10" I.Cedar, I scribe "1/4 S27 BT" bears S.70°E., 19.6  
ft.  
Brass cap is set in decayed D.Fir root collar.

FD. BC & BT - Set 6' steel post 2' North by D. Edwards,  
1/2007 - M152-14

continued next page

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2804, surveyed Aug/Sept 2015 - (DCS0 records Vol. 58 Page 23423-5 & Plat T29-3 2017-1)

-----  
The ¼ sec. cor. of secs. 27 & 28, perpetuated by Byron, in 1959, subsequently perpetuated by Shaner, in 1979, monumented with an iron post, 1¼" dia., firmly set, projecting 17" above ground, with brass cap (properly) mkd. from which the remains of the original BTs reported by Byars in 1881

A root hole bears N.40°E., 11.9 ft. alongside of which is a fallen, decayed fir snag, size indeterminate, with no marks visible. (Record, S.40°E.)

A decayed fir stump, 40" dia., bears N.53°W. 11.2 ft., with a hollowed blaze, no marks visible. (Rec. N.40°W.) and the remains of a BT mkd. by Byron

A burnt & hollowed cedar snag, 40" dia., bears N.42°W., 33.1 ft. with scribe marks ¼ S28 CS visible on a partially healed blaze.

and a bearing tree mkd. by Shaner

A cedar, 19" dia., bears S.67½°E., 19.3 ft., with a healed blaze.

and a BT of unknown origin

A maple, 15" dia., bears S.27½°E., 8.2 ft., with a healed blaze.

and a new bearing tree

A madrone, 7" dia. bears S.26¼°W., 21.4 ft., mkd. ¼ S28 BT in the bark. BT has a 2½"x¼" (Mag Nail) driven at the base on right side center