

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

| | |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page 6344)

Set Dogwood post for 1/4 sec. cor., from which
A Laurel 12" dia., bears North, 27 lks. dist.
A Laurel 20" dia., bears S.48°W., 9 lks. dist.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO rec Vol 33 Pg 13806)

The 1/4 sec. cor., determined at record bearing and distance from the original bearing trees:

A Madrone 18" dia, bears North 27 lks., no marks remaining on rotted blaze.

A Madrone 30" dia. bears S.48°W., 9 lks no marks remaining

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 21" in the ground, with brass cap mkd:

T 29 S R 3 W
1/4 S 3
S 10
1964

from which new bearing trees:

A Fir 7" dia., bears N.78 1/2°E., 70 lks., mkd. 1/4 S3 BT

A Cedar 8" dia., bears S.23°W., 31 1/2 lks., mkd. 1/4 S10 BT.

Fd. OK by D. Edwards, Oct. 1998 - M130-67

BLM resurvey by George M. Winter, Cadastral Surveyor under Group No. 2654, surveyed Oct./Nov. 2012 - (DCSO records Vol. 58 Page(s) 23027)

The 1/4 sec. cor. of secs. 3 and 10, monumented with an iron post, 2 1/2" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd.

from which the remains of an original bearing tree

A decayed madrone stump, bears S.48°W., 5.9 ft., with no marks visible.

and remains of a bearing tree mkd. by Beck in 1964-65

A cedar snag, 15" dia., bears S.23°W., 20.8 ft., with a healed double blaze.

and new bearing trees

A fir, 8" dia., bears S.76 1/4°W., 18.8 ft., mkd. 1/4 S10 BT.
(Mag Nail driven at the base on left side center)

A cedar, 15" dia., bears N.45 3/4°W., 35.2 ft., mkd. 1/4 S3 BT.

Corner is located 288 ft. W. of an intermittent stream, course S.

Fd. BC 8/2018 by N Hibbs, 2018-0027A-B