

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6337)

-----  
Set Fir post for the ¼ sec. cor., from which  
A Fir 8" dia., bears N.80°W., 3 lks. dist.  
A Fir 8" dia., bears East, 8 lks. dist.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13802-03)

-----  
The ¼ sec. cor., monumented with rotted portions of the original corner post, below the surface of the ground, from which the remains of an original bearing tree:

A rotted Fir root crown, size indeterminate, bears East, 8 lks. dist.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 29 S R 3 W  
                  ¼  
                  S 10 | S 11  
                  1964

from which new bearing trees:

A Fir 12" dia., bears N.67°E., 35 lks. dist., mkd. ¼ S11 BT.

A Fir 7" dia., bears N.84½°W., 123 lks. dist. mkd. ¼ S10 BT.

Corner falls in old rail fence which bears N. and S.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, and crew - June 28, 1967 - C.S. File 52/126-150

-----  
Found - 1964 Cadastral brass cap, firmly set and properly marked.

12" now 13" Fir N.53°E., 23.1 ft., alive, scribe marks visible on partially healed blaze. (Rec. N.67°E.)

7" now 8" Fir N.84½°W., 81.2 ft., alive, scribe marks visible on partially healed blaze. (This tree to be removed for cultivation of field.)

New BT - 6" D.Fir S.20°W., 92.7 ft. mkd. ¼ S10 CS BT.

This corner lies 40 ft. East of roadway, course N & S.

Fd. OK by D. Edwards, Oct. 1998 - M130-67

continued next page

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2154, Surveyed April/May 2007 - DCS0 records Vol. 57 Page(s) 22568  
-----

The ¼ sec. cor. of secs. 10 and 11, monumented with an iron post, 2 1/2" dia., firmly set, projecting 5" above the ground, with brass cap (properly) mkd. from which the remaining bearing tree mkd. by Beck in 1964-65  
A fir, 22" dia., bears N.52¼°E., 23.1 ft., with a healed blaze. (Record, N.67°E.)  
and a bearing tree mkd. by Tracy, in 1967  
A fir, 24" dia., bears S.19¾°W., 93.3 ft., with a healed double blaze.  
Corner is located 12.0 ft. East of a woven wire fence, with fences extending N. and S.

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff Lorsung - 10/24/2018 (Filed 11/10/2021) - C.S. File 67/49-24  
-----

Found - A 2½" dia. Iron Pipe with ¾" brass cap firmly set and projecting 3" (properly) marked  
BTs by Beck 1965 -  
A 22" D.Fir bears N.52¼°E., 23.1 ft. (rec N.67°E.)  
BTs by Tracy in 1967 -  
A 28" D.Fir bears S.19¾°W, 92.7 ft.  
New - A 20" D.Fir bears S.23°E, 20.0 ft scribed "¼ S11 CS"  
"BT"  
A 17" D.Fir bears N.7½°W., 7.3 ft scribed "¼ S10"  
"CSBT"  
Note - All new BTs measured to side center root crown marked with a 2½" PK nail and double blazed  
All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown to a magnetic PK nail  
Monument is located 45 ft. East of the center of roadway.  
Compass declination 15°E.