

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6335)

Set Maple post for the ¼ sec. cor. from which
A fir, 18" dia., bears N.3°W., 22 lks.
A hemlock, 10" dia., bears S.10°W., 30 lks.

BLM Dependent resurvey by Timothy J. Moore & A. Bert Skeesick, Cadastral Surveyors under Group #2033, surveyed Sept. 2002/June 2003 (DCSO rec. Vol. 55 pg(s) 21325-6)

Point for the ¼ sec. cor. of secs. 23 & 26 at proportionate dist.; there is no remaining evidence of the orig. cor.

Set a stainless steel post, 28" long, 2½" dia., 23" in the ground, with brass cap mkd.

T29S R3W
¼ S 23
 S 26
2003

from which

A fir, 14" dia., bears N.11°E., 14.6 ft., mkd. ¼ S23 BT.

A fir, 14" dia., bears S.58¾°E., 18.4 ft., mkd. ¼ S26 BT.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description

From this point, an iron pipe, ¾" dia., loosely set, projecting 2" above ground, bears N.10°14'09"W., 1.00 ft., established without authority during a 1979 Bureau of Land Management administrative survey. This monument is not accepted as the true cor. location and is removed and buried alongside the stainless steel post.