

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page 6336)

Set Maple post for ¼ sec. cor. from which
A laurel, 20" dia., bears S.60°E., 44 lks.
A fir, 24" dia., bears N.78°W., 43 lks.

BLM Dependent resurvey by Timothy J. Moore & A. Bert Skeesick, Cadastral Surveyors under Group #2033, surveyed Sept. 2002/June 2003 (DCSO rec. Vol. 55 pg(s) 21330-1)

Point for the ¼ sec. cor. of secs. 14 & 23 at proportionate dist.; there is no remaining evidence of the orig. cor.
Set a stainless steel post, 28" long, 2½" dia., 26" in the ground, with brass cap mkd. T29S R3W

¼ $\frac{S\ 14}{S\ 23}$
2003

from which

A fir, 13" dia., bears S.16½°W., 21.3 ft., mkd. ¼ S23 BT.
A fir, 13" dia., bears N.63°W., 23.3 ft., mkd. ¼ S14 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description

Deposit a magnet in a white plastic case at the base of the stainless steel post.

From this point, an iron pipe, 1" dia., firmly set, projecting 2" above ground, bears N.8°35'02"E. 1.49 ft. established without authority during a 1979 BLM admin survey. This monument is not accepted as the true cor. location and is removed and buried inside the stainless steel post.