

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 2 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6338)

Set Cedar post for ¼ sec. cor., from which
A Laurel 14" dia., bears N.30°E., 31 lks. dist.
A Fir 18" dia., bears S.55°E., 17 lks. dist.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13804)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 29 S R 3 W

¼ $\frac{S}{S}$ $\frac{2}{11}$

1964

from which

A Fir 6" dia., bears N.19°E., 55 lks. dist., mkd. ¼ S1 BT
A Fir 17" dia., bears S.48½°E., 36 lks. dist., mkd. ¼ S11 BT.

Douglas Co. Surveyors Office - R.B. Kimberling; P.L. Earle, crew - June 8, 1977 - C.S. File 59/34-31

Found - 2½" I.P. with 3¼" 1964 Cadastral brass cap 3" above ground, properly marked.

6" now 8" D.Fir bears N.20°E., 35.3 ft. (Rec. N.19°E., 36.3 ft.) with well healed blaze.

17" now 20" D.Fir bears S.48½°E., 23.8 ft. with well healed blaze.

Bearings and distances recorded on tags did not agree with records or actual measurements to brass cap.

DID NOT RENEW.

Fd. OK Oct. 1999 by D. Edwards - M133-43