

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6328)

-----  
Set a Fir post for ¼ sec. cor., from which  
A Fir 18" dia., bears S.50°W., 30 lks. dist.  
A Fir 10" dia., bears N.60°W., 38 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - July 28, 1958 - C.S. File 49/47-5

-----  
Found - Orig. 18" now 36" Fir, shows good bark scribing "BT 0", S.50°W., 19.8 ft.  
Orig. 10" now 30" Fir, N.60°W., 25.1 ft. Previously opened wood scribed "BT". Checks for ring count. (Rec. dist. 25.1 ft., I find should be 22.6 ft.)

Set Brass cap at cor. mkd: County Surveyors Office

T 29 S R 3 W  
¼ S 25  
S 36  
1958

New BTs- 9" R.Fir bears N.65°E., 26.5 ft. scribed ¼ S25 CS BT  
10" R.Fir bears S.43½°E., 30.6 ft. scribed ¼ S36 CS BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R.G. Boyd - May 13, 1959 - C.S. File 42/315-7

-----  
We add these two bearing trees to corner since we are logging both original bearing trees as shown by Byron in 1958:  
New BTs- 10" Fir bears N.72°W., 21.7 ft. mkd. ¼ S25 R3W BT.  
8" Fir bears S.13°E., 30.0 ft. mkd. ¼ S36 W.M. BT.

BLM Dependent resurvey by Timothy J. Moore & A. Bert Skeesick, Cadastral Surveyors under Group #2033, surveyed Sept. 2002/June 2003 (DCSO rec. Vol. 55 pg(s) 21321-2)

-----  
The ¼ sec. cor. of secs. 25 & 36, perpetuated by the Douglas Co Surveyors Office, in 1958, & by Markham, in 1959, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees

A sawed decayed fir stump, 32" dia., bears S.50°W., 19.8 ft., with scribe marks BT visible on a bark blaze.

A sawed decayed fir stump, 24 ins. diam., bears N.60°W., 22.9 ft., with scribe marks BT visible on an opened blaze. (Record, 25.1 ft.)

continued next page

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the remains of a bearing tree mkd. by the Douglas County Surveyors Office

A decayed stump, size and species indeterminate, bears S.56°E., 30.4 ft., with no marks visible.

and the remains of a bearing tree mkd. by Markham

A decayed stump, species indeterminate, 10" dia., bears N.69¾°W., 22.0 ft., with no marks visible.

and new bearing trees

A fir, 7" dia., bears N.39°E., 12.6 ft., mkd. ¼ S25 BT.

A fir, 9" dia., bears S.81½°E., 11.5 ft., mkd. ¼ S36 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description

Ron Quimby - Crew: N. Fromdahl, R Heichel & R Vincent - 1/2018 - C.S. File 65/101-20

- 
- Found - 2½" DCSO brass cap (properly mkd)
  - 12" Fir S.81½°E., 11.5 ft. good scar.
  - 8" Fir snag 10' tall N.39°E., 12.6 ft good scar.
  - 32" Fir stump S.50°W., 19.8 ft. good scar.
  - 24" Fir stump N.60°W., 22.9 ft. good scar.
  - New - 14" Fir N.73°E., 32.1 ft. scribed ¼ S25 BT
  - 18" Fir S.56°W., 33.4 ft. scribed ¼ S36 BT
  - 22" Fir N.45°W., 3.9 ft. scribed ¼ S25 BT
  - Note - Compass decl. 15½°E.