

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 1 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6324)

Set Fir post for 1/4 sec. cor., from which
A Fir 12" dia., bears N.32°W., 10 lks.
A Fir 12" dia., bears S.52°E., 10 lks.

GL0 resurvey by William N. Gibb, Deputy Surveyor, under Contract #783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5548)

Stake has been destroyed; bearing trees standing, marked as described by the Surveyor General.
Set granite stone, 6 x 10 x 14 ins., 10" in the ground for 1/4 sec. cor., marked 1/4 on S. face.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - Feb. 2, 1960 - C.S. 49/47-10

Found - Orig. 12" now 18" Fir S.52°E., 6.6 ft. I open and find good scribing "1/4S".
Orig. 12" now 16" Fir N.32°W., 6.6 ft., center rotted, no scribing found.
Corner stone, not found.

Set Brass cap at cor. mkd: County Surveyors Office
T28S
N 1/4 S 1 T29S R3W
1960

New BTs- 24" R.Cedar bears S.43°E., 34.5 ft. scribed N 1/4 S1 CS BT.
5" R.Fir bears S.67°W., 15.0 ft. scribed N1/4 S1 CS BT.

Fd. OK, Dec. 1966 by V. Tracy, DCSO

BLM resurvey by James J. Carlson, Cadastral Surveyor, under Group #892, surveyed June/July 1976 - (DCSO records Vol. 39 Page(s) 15843-44)

The 1/4 sec. cor., perpetuated and recorded by Byron in 1960, monumented with an iron post, 1 1/2" dia., firmly set, projecting 18" above ground with brass cap mkd:

T 28 S R 3 W
N
1/4 cor. S 1
T 29 S R 3 W
1960

(Cont. Next Page)

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 1 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the original bearing trees
A Fir snag 14" dia., bears N.38½°W., 10 lks. dist., with fragmentary scribe marks visible on opened blaze. (Rec. N.32°W.)
A decayed Fir stump 16" dia., bears S.60°E., 10 lks. dist., with scribe marks ¼ S visible on open blaze. (Rec. S.52°E.)
and the remains of bearing trees mkd. by Byron
A Cedar 28" dia., bears S.43°E., 46 lks. dist., with fragmentary scribe marks visible on open double blaze.
A Fir snag 6" dia., bears S.67°W., 19 lks. dist. with healed double blaze.
and new bearing trees
A Cedar 15" dia., bears S.77½°E., 86 lks. dist. mkd. ¼ S1 BT.
A Fir 8" dia., bears S.26 ¾°W., 66½ lks. dist., mkd. ¼ S1 BT.