

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 700441

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19 only, T29-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6228)

Set a basalt stone 18x12x7 ins., 12" in the ground for cor. of secs. 18 and 19, marked with 3 notches on N. and S. edges, from which

- A Fir 42" dia., bears N.1°45'E., 263 lks. dist. mkd. T29S R2W S18 BT.
- A Fir 24" dia., bears S.32°E., 217 lks. dist. mkd. T29S R2W S19 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Nov/Dec. 1962 - C.S. File 52/126

Found - Orig. 42" now 48" Fir N.1°45'E., 167.0 ft. (not 173.6 ft.), shows good bark scribing and old scar
Do not find either corner stone, but both orig. bTs for E. 1/4 Cor. Sec. 13.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S
R3W $\frac{S}{S}$ $\frac{18}{19}$ R2W
1962

New BTs- 12" R.Fir bears S.12½°E., 21.4 ft. mkd. S19 T29S R2W CS BT.
8" R.Fir bears N.87°E., 22.6 ft. mkd. S18 CS BT.
Corner is on steep North slope.

Fd. and used in BLM resurvey by James J. Carlson, Cadastral Surveyor, under Group #892, surveyed June/July 1976 - (DCSO records Vol. 39 Page(s) 15839)