

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 039010

PRIMARY CORNER DESCRIPTION NE cor. Hans Weaver DLC #39

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated June 8, 1857

Set post NE. cor., from which
An Oak 15" dia., bears N.67°E., 67 lks.
An Oak 15" dia., bears S.5°W., 235 lks.

A. Boyer, Douglas Co. Surveyors Office - Wit: Ted
Shellabarger and Delbert Trask - Oct. 12, 1938 - C.S. File
16/4 and M 3-67

Found one of two original BTs (SW) okay. BT to NE. dead.
Set 4 x 4 Oak post and one new BT:
An 8" W.Oak N.1°E., bark blaze, 6 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike
Darby; Wm Stoffel crew - April 1963 - C.S. File 52/126-110

Found - 8" now 8" W.Oak N.1°E., 6.0 ft., shows good
scribing.
Also find scribed post at corner.
Orig. BTs not found.
Fence corner runs West and South.
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 4 W

NE DLC 39 |
1963
New BT - 12" R.Fir bears S.24°W., 50.8 ft. scribed NE DLC 39
CS BT.

Douglas Co. Surveyors Office - John Powell, Frank Jones and
W. Penley, crew - 1969 - C.S. File 49/67-44

Found - No trace of 1963 DCSO brass cap.
12" D.Fir now 13", S.24°W., 50.0 ft., pitched over,
scribe visible.
No trace of NE. BT.
This corner falls in small slide which now looks as if it
will not slide anymore.
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 4 W N.E.

D.L.C. #39 |
1969
New BT - 8" D.Fir N.41°W., 21.2 ft. mkd. NE DLC 39 CS BT

(Cont. Next Page)

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 039010

PRIMARY CORNER DESCRIPTION NE cor. Hans Weaver DLC #39

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey by James E. Jelley and Lynn Roseberry Cadastral Surveyors under Group #'s 255; 701; 938 - Surveyed July 1967/Oct 1977 (DCSO records Vol. 39 Page(s) 15902)

The NE. cor. of DLC #39, perpetuated and recorded by Boyer in 1938, and further perpetuated and recorded by Byron in 1963, and again perpetuated and recorded by Byron in 1969, monumented with an iron post, 1" dia., firmly set, projecting 2" above ground, with mkd. brass cap.

from which the remains of the original bearing trees:

A root hole bears N.67°E., 67 lks. dist., with a down and decayed Oak alongside, 24" dia., no marks visible.

A root hole bears S.6°W., 235 lks. dist. with a down Oak alongside 24" dia, with fragmentary scribe marks visible on opened and burned blaze. (Rec. S.5°W.)

and a bearing tree mkd. by Byron in 1963

A Fir 12" dia., bears S.24¼°W., 75 lks. dist. with healed double blaze.

and a bearing tree mkd. by Byron in 1969

a Fir 7" dia., bears N.41°W., 32 lks. dist. with scribe marks NE DLC #39 CS BT visible on open double blaze.

Corner is located in head of ravine, drains SW.

Fd. OK, Aug. 1993 by B. Shaner - RM 3-79