

PRIMARY CORNER DESCRIPTION NW Cor. Hans Weaver DLC #39

Alias	Description

<p>Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated June 8, 1857</p> <p>-----</p> <p>A Fir 40" dia., NW. cor., from which A Fir 10" dia., bears S.10°E., 34 lks. A Fir 12" dia., bears S.40°W., 27 lks.</p>
<p>W.H. Wood, Deputy Co. Surveyor - Wit: W.S. Crear and A.C. Redifer - Nov. 3-6, 1925 - Vol. 3 Pg. 229 (and "old" corner book pg. 123)</p> <p>-----</p> <p>Set Iron pipe and rescribed trees S.40°W., 27 lks. S.10°E., 34 lks., Cl. 39 BT CS.</p>
<p>A. Boyer, Douglas Co. Surveyor - Wit: Ted Shellabarger and Delbert Trask - Oct. 12, 1938 - C.S. File 16/4 and M 3-67</p> <p>-----</p> <p>Original BTs dead. Stump of original Fir corner tree still standing. New BT: Red Fir 24" dia., bears N.87½°W., 30 ft.</p>
<p>Cor. tied in BLM survey by Roseberry and Jelley, Group #'s 155, 701 and 938, surveyed July 1967/Oct. 1977 - (DCSO records, Vol. 39 Page 15884)</p>
<p>Do. Co. Surveyors Office - Randall Smith & Stephen Flause - Sept. 7, 1993 - C.S. 64/46-13</p> <p>-----</p> <p>Found - 5/8" I.R. protruding 6" above ground (not of Rec.) Fd. in rotted remains of old deteriorated stump. (Orig. Cor Tree)</p> <p>In renewal by Wood, 1925, corner is said to be monumented with iron pipe. In Vol. 3 Pg 229, notes monument as being an iron pin. This 5/8" I.R. does not look nearly old enough to be 1925 iron pipe.</p> <p>24" now 25" dia. 3 ft. high D.Fir stump with bark scribing "CS BT" bears N.87½°W., 31.4 ft. (Rec. N.87½°W., 30 ft., dist. is a face measurement). Root hole bears S.40°W., 20 ft., (Rec. S.40°W., 17.8 ft.) possible face to face measurement an addition of half 40" cor. tree and half 12" BT would add up to approx. 20 ft.</p> <p>Rotted remains of orig. SE. BT. found near rec brg. & dist. (S10°E., 22.4 ft.).</p>

(Cont. Next Page)

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 039020

PRIMARY CORNER DESCRIPTION NW Cor. Hans Weaver DLC #39

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Monument set:

2 3/8" dia. DCSO BC on a 1 3/8" by 32" long I.P. at a position that I felt most possible from remaining evidence of corner. BC/IP position lies near center of corner tree, determined from remaining evidence of stump. (See accessories fd.)

Cap mkd:

Douglas County Surveyors

T29S

R NW Cor

4 | DLC 1993

W | 39

DCSO BC/IP protrudes 8" above ground. 5/8" I.R. bears N.49°E., .9 ft. from BC/IP.

New BTs -Most westerly 9" maple of a cluster of maples is double blazed and scribed "NW DLC 39 CS BT". Base of scribed trunk bears S.14¼°E., 23.3 ft.

11" dia., D.Fir double blazed & scribed "NW DLC 39 CS BT" bears N.65 3/4°W., 19.4 ft.

7" dia., Cedar Double blazed & scribed "NW DLC 39 CS BT" bears N.32¼°W., 21.1 ft.

9" dia., D.Fir double blazed & scribed "NW DLC 39 CS BT" bears N.6°W., 25.3 ft.