

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 100600

PRIMARY CORNER DESCRIPTION Sec Cor 6, 7; 1, & 12 T29-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - James E. Freeman, under Contract #1 dated May 28, 1851 (DCSO records, Vol. 15 Page 6351)

-----  
Set post, cor. of Secs. 1, 6, 7, & 12, from which  
A Fir, 12" dia., bears S.50°E., 31 lks.  
A Fir, 14" dia., bears N.42°E., 70 lks.  
A Fir, 9" dia., bears N.57°W., 70 lks.  
A Redwood, 30" dia., bears S.57½°W., 65 lks.

Robert M. Thompson - For: Patrick Lumber Co. - June 1958 - C.S. File 41/62-1

-----  
Fnd - 24" stunted D. Fir which U.S. notes call "Redwood", S.57½°W., 43'. Find scribe "5W, S1(2)" (2 rotted out). Other BTs burned.

Set - 6x10x12 Conglomerate stone & new BTs:  
40" D. Fir S.75°30'W., 46.0'  
14" I. Ced. N.23°40'W., 36.4'  
40" D. Fir, N.88°40'E., 57.2'  
17" I. Ced. S.34°20'E., 21.2'

This corner falls 6' E. of Little Lick Cr. & approx. 120' E. old log road.

Doug. County Surveyors Office - James W. Byron, Deputy - Dale McFarland - John Powell - March 1962 - C.S. File 49/64-78

-----  
Found - Stone at corner & BTs as recorded by Thompson, except SW BT now stump and NE BT down.

Set - Brass cap alongside Cor. stone & mkd:  
County Surveyor's S 1 | S 6 T29S  
Office 1962 R5W S 12 | S 7 R4W

Note - Corner is 6' East of Stream.

New BT - 5" R. Fir, bears N.45½°E., 6.7' Scribed S 6 CS BT.

FD OK by Donald Bentz, 11/87 - M 105-19

FD OK by Raymond Brown, LS 2391 - Jan. 1994 - 1994-0021 A&B

Harvey Christensen - For: McDougal Brothers & Rosboro Lumber Co. - Nov. 1997 - M 128-14

-----  
Found - 1962 DCSO 2½" BC  
18" D.Fir N.50°E., 7.1 ft. healed face.  
6" D.Fir S.42°W., 44.7 ft. open face.  
30" I.Cedar S.32°E., 22.2 ft. healed face.  
28" I.Cedar N.21°W., 37.3 ft. healed face.

continued next page

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 100600

PRIMARY CORNER DESCRIPTION Sec Cor 6, 7; 1, & 12 T29-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Wayne L. Rogers, Dale T. Bedell, Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Surveying Technician, under Group #1625 surveyed Sept. 1991 thru April 1993 - (DCSO records Vol. 52 Page(s) 19778-9)

-----  
The cor. of secs. 1, 6, 7, & 12, perpetuated by Thompson, in 1958, determined from the remains of the original BTs no longer in existence, further perpetuated by Byron, Deputy County Surveyor, in 1962; monumented with an iron post, 1¼" diam., firmly set, projecting 12" above ground, with properly mkd. brass cap mkd.

from which the remains of bearing trees mkd. by Thompson

A burnt and sawed fir stump, size indeterminate, bears N.87 3/4°E., 90 lks., no marks visible.

A cedar, 29" diam., bears S.32°E., 32 lks., with healed double blaze.

A sawed fir stump, 40" diam., bears S.76°W., 72 lks., with scribe marks 29S R5W visible on bark blaze.

A cedar, 29" diam., bears N.24½°W., 56 lks., with healed double blaze.

and a bearing tree mkd. by Byron

A fir, 16" diam., bears N.41½°E., 12 lks., with healed double blaze.

and a new bearing tree

A fir, 5" diam., bears S.40¼°W., 68½ lks., mkd. T29S R5W S12 BT.

Kris DeGroot - 12/2010 - M157-36

-----  
Lat: 43°04'12.739715" N Long: 123°13'34.583785" W.  
Found a 1962 DCSO BCIP by J. Byron, per C.S. 49/64 and accessories of record per 1991 USBLM dependent resurvey.

James Klein - Michael Erickson - Douglas Popham - For:  
Williams/Pacific Connector Pipeline - 6/2015 - M166-38 A-D

-----  
Found - 2.5" brass cap stamped County Surveyors Office dated 1962  
23" Fir with healed face & tag no date, N.50°30'E., 7.0'  
39" cedar with healed face & tag no date, S.32°E., 22.2'  
17" fir with healed face & tag dated 4/91, S.50°W., 45.1'  
40" cedar with healed face & tag no date N.21°W., 37.3'