

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 141400

PRIMARY CORNER DESCRIPTION South 1/4 Cor for Sec 18 only

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Please Note: BLM survey by Boyd Peterson, Group #1394, surveyed Aug. 1987/Jan. 1988 found corner established by Markham to be erroneously positioned. Peterson did not establish this corner. (See Vol. 48 Page 18514)

Survey by John H. Markham, Jr. - Wit: C. C. Pruitt - April 27, 1955 - C.S. File 41/386-1

Set by proportional measurement.
At a point 2714 ft. East of the SW. corner of sec. 18 and 2622 ft. West of the SE corner of sec. 18, I Set 3/4" x 24" Iron pipe for 1/4 corner, from which
 A 24" Fir bears N.52°E., 8.0 ft., bark scribed 1/4 S18 BT.
 A 23" Fir bears N.43°W., 21.6 ft. bark scribed 1/4 S18 BT.
N. 1/4 cor. sec. 19 bears West 60.0 ft.
Dry wash bears West 100.0 ft.

Peterson established the No. 1/4 Cor. sec. 19 and found the above Markham cor. for 18 to bear S.40°04'00"E., 1.160 chs.

Dan Saily- For: Lone Rock Timberland Co. - 9/2021 - M180-11

Set - 5/8"x40" iron rod with aluminum cap marked LONE ROCK
TIMBER T29S R4W 1/4 S18 2021 85006 PLS
13" D.Fir bears N.29 3/4°E., 9.9 ft. We scribe 1/4 S18 BT
and tag
16" D.Fir bears N.23 1/2°W., 27.0 ft. We scribe 1/4 X BT and
tag
14" D.Fir bears S.21°E., 18.0 ft. We scribe X BT and
tag. We marked this tree in section 19 because the
BTs in section 18 will likely be cut in the next 3-5
years.
Found Markham iron pipe badly bent to the West bears
S.1°09'18"E., 57.29 ft to where the pipe enters the
ground
BTs for Markham iron pipe -
26"x6' tall D.Fir stump found at record N.52°E., 8.0
ft visible "BT" bark scribe and BLM tag
30x6 tall D.Fir stump found at record N.43°W., 21.6 ft.
No visible bark scribing, has BLM tag
Note- South 1/4 corner lies on West facing slope approximately
100 ft West of gravel road. Top of South 1/4 corner
monument is 0.1 ft above ground level. We place 5 1/2
ft. tall steel U-POST 1.0 ft East.
BT distances are to an aluminum nail in the side center
and bearings were derived from angular measurements
to an aluminum nail in the face of the tree.

cont.

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 141400

PRIMARY CORNER DESCRIPTION South 1/4 Cor. for Sec. 18 only

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Fd as per rec. 11/2022 - B. Knapp - M181-51