

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7, 8, 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6384)

Set cor. secs. 7, 8, 17 and 18, from which
An Ash 6" dia., bears N.66°E., 19 lks. dist.
A Fir 12" dia., bears S.43°E., 50 lks. dist.
A Fir 18" dia., bears S.10°W., 54 lks. dist.
A Maple 18" dia., bears N.89°W., 72 lks. dist.

GLO survey by W.F. Briggs, Deputy Surveyor, under Special Instructions, dated Jan. 18, 1899 - (DCSO records Vol. 15 Page(s) 6415)

Post and witness trees all gone, washed out by high water except the Ash, 6" dia., mentioned in originl notes, which is still standing.
Made new post 4" sq., 3 ft. long, 24" in the ground, mkd. R4W S7 on NW. face; T29S S8 on NE. face; S17 on SE. face; S18 on SW. face; with 5 notches on E. and 4 notches on S. edges, from which made new witness trees to wit:
Fir 6" dia., bears S.33½°W., 13 lks. scribed S18 T29S R4W BT.
Fir 5" dia., bears N.89½°W., 23 lks. scribed S7 BT.
No tree near in S17.

Ben B. Irving, County Surveyor - J.W. Byron; R.G. Irving; John Fee, crew - March 1954 - C.S. File 45/234

Location indefinite but found 24" Fir tree at location that would fit BT established by Briggs, 1899, N.89½°W., 23 lks. from corner. This tree does not show identifiable axe blazes but old fence E. and W. tied to it with old picket gate on E. side. The corner as located from this tree would be over the bank where N. Myrtle Creek has washed. The distance fits very close to old creek bank noted by Hathorn at 76.30 chs. East of cor. secs. 7, 12, 13 and 18. Myrtle Creek has changed its channel and is now East of the corner though right creek bank is identifiable. By using this location for the corner, We find it to be S.89°59'E., 5177.15 ft. from the corner 7, 12, 13 and 18. This location fits old fence line claimed by owners to be property lines.
The ¼ sec. corner to secs. 8 & 17 is S.89°59'E., 2583.41 ft. from this location.
The ¼ sec. corner to secs. 7 & 8 is N.0°18'W., 2711.06 ft. from this location.
A traverse was run South but ¼ cor. 17 & 18 has been lost as is the CC sec. cor. 17 & 18 and the cor. 19 & 20 on the S. bdy. sec. 19. (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7, 8, 17 and 18

Alias	Description
Alias	Description
Alias	Description
Alias	Description

An old Oak with ancient line blazes was found South 5390.84 ft. and East 502.71 ft. from this corner location. As the corner location fell on a sand bar below the present creek bank and subject to wash, a WITNESS CORNER was set at the base of the tree noted as follows:
Set a 1" x 36" Galv. Iron pipe with brass cap at base of tree for a W.C. to the sec. cor. mkd. "County Sur. Office W.C. T29S R4W 1954", from which
A Fir 24" dia., bears N.89½°W., 3.0 ft.
A 24" Cedar N.27°E., 31.8 ft.
A 10" Cedar S.47°50'W., 36.8 ft.
all blazed and scribed T29S R4W W.C. S7-8-17-18 CS BT.
A 14" Cedar N.7°W., 93.2 ft.

Cor. Fd. and tied in BLM survey by Boyd W. Peterson, under Group #1394, surveyed Aug. 1987/Jan. 1988 - (DCSO records, Vol. 48 Pg. 18517 and 18518)

The witness cor. established and recorded by Irving, 1954, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground with brass cap.
from which the bearing trees mkd. by Irving:
A Cedar 32" dia., bears N.38¼°E., 50 lks. dist. with fragmentary scribe marks visible on partially healed blaze.
A Cedar 20" dia., bears S.58 3/4°W., 56 lks. dist. with healed double blaze.
A Fir 35" dia., bears N.88 3/4°W., 5 lks. dist. with scribe marks BT visible on the bark.
A Cedar 30" dia., bears N.3°W., 131 lks. dist. with healed double blaze.

Fd. OK, Dec. 1994 by R. Dolan - M 121-29
Fd. Ok by D.Edwards, 10/96, M 126-12.

Fd. & used on BLM dependent resurvey by Wayne L. Rogers, Dale T. Bedell, Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Surveying Technician, under Group #1625 surveyed Sept. 1991 thru April 1993 - (DCSO records Vol. 52 Page(s) 19768)