

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 231100

PRIMARY CORNER DESCRIPTION C C for Secs. 5 & 6 only, T30-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7097)

For closing cor. to secs. 6 and 5, I set a Laurel post 4½ ft. long, 4" square, 24" in the ground, marked CC T30S R4W on S. face; S5 on E. face; S6 on W. face, and 1 notch on W. and 5 notches on E. faces, from which
A Pine 36" dia., bears S.11°E., 163 lks. dist. mkd. T30S R4W S5 BT.
A B.Oak 8" dia., bears S.17°W., 208 lks. dist. mkd. T30S R4W S6 BT.

Survey by John H. Markham, Jr. - Wit: Wm. Markham - Dec. 5, 1949 - C.S. File 40/239-1

At a point 650.0 ft. West of the So. 1/4 Cor. of Sec. 32, I set a 3/4" x 24" Iron pipe 14" in the ground, from which
23" Fir bears N.10°W., 19½ ft. mkd. S32 2880 BT.
4" Laurel bears S.25°W., 40.0 ft. mkd. S6 2880 BT.
3" Laurel bears S.58°E., 34.0 ft. mkd. S5 2880 BT.
A diligent search was made for original BTs but no evidence was found. In checking notes, I found the ¼ cor. was established from 1 BT. I used the intersection of both original BTs and all of the calls checked, including bearings.

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20123-4)

True point for the closing cor. of secs. 5 and 6.
Set a stainless steel post, 28" long, 2½" diam., 26" in the ground, with brass cap mkd.
T29S R4W
S 32
S 6 | S 5
C C
T30S R4W
1994

from which
A fir, 23" diam., bears S.13 3/4°E., 55 lks., mkd. T30S R4W S5 CC BT.
A fir 20" diam., bears S.58¼°W., 55 lks., mkd. T30S R4W S6 CC BT.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

continued next page

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 231100

PRIMARY CORNER DESCRIPTION C C for Secs. 5 & 6 only, T30-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From this point, a point reestablished as the closing cor. of secs. 5 & 6 by Markham, in 1949, bears North, 0.049 chs.; monumented with an iron pipe, 1" diam., firmly set, projecting 8" above ground, from which the remains of bearing trees mkd. by Markham:

A fir, 38" diam., bears N.12½°E., 31 lks., with fragmentary scribe marks visible on the bark.

A madrone snag, 5" diam., bears S.55 3/4°E., 50 lks., no marks visible on double decayed blaze.

A madrone, 9" diam., bears S.26¼°W., 60 lks., with healed blaze.

It was determined that Markham used proper control in an east and west direction and improper control in a north and south position, therefore this point was accepted longitudinally but rejected latitudinally.

From this same point, the ¼ sec. cor. of sec. 32 only, T29S, R4W bears S.88°54'27"E., 9.820 chs.

Ronald Quimby - For: James Little - April 1999 - M 129-44

Found - BLM brass cap, 1994 (resurvey not filed at this time) from which:

A 24" Fir bears S.13°03'14"E., 36.6 ft. (55 lks) healed face.

A 22" Fir bears S.58¼°W., 36.3 ft. (55 lks)

A 38" Fir bears N.12½°E., 20.5 ft., fragmentary bark scribes visible.