

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 5; Sec. 32 T 28-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, Contract # 44 dated May 30, 1854  
(DCSO records Volume 13, Pg. 5606-7)

-----  
Set 1/4 sec. post at proper distance from which:  
A Dogwood, 4" dia., bears N.5°W., 12 lks. dist.  
A Yew, 4" dia., bears S.43°W., 13 lks. dist.

-----  
South boundary of T.28-4, surveyed by W.H. Byars, Contract  
# 376 dated Jan. 22, 1881. (DCSO records Vol. 13 Pg. 5613)

-----  
Set a yew post for 1/4 sec. cor. from which:  
A Fir, 8" dia. bears N.12°W., 43 lks. dist.  
A W.Fir, 8" dia. bears S.45°W., 10 lks. dist.  
Note: Per note in Byars 1881 survey "In the execution of this  
work I found that the old line established for the S bdy of  
this Township was glaringly at fault..." Byars set his own  
corners. See CS 63/166 BLM opinion file T28-4 (added  
4/7/2010)

-----  
Frank Cain Co. Surveyor, witnesses, F.J. Cole, J.T. Black -  
Wm. Berdine. Surveyed for W.H. Lawrance. May 1915.  
(DCSO records Vol. 2 pages 222-226 & 231-232, also FB no.  
34, pages 14-24).

-----  
Renew corner from stumps of orig. Wit. trees. Set charred  
post from which:  
A R.Fir, 10" dia. bears S.39°05'E., 56 lks. dist.  
A R.Fir, 5" dia. bears S.28°W., 60 lks. dist.

-----  
G.J. Wenderoth Deputy Co. Surveyor, (DCSO records M28-78)  
Nov. 1946.

-----  
Renewed Cor. from old BTs.  
Set - 1 1/4" iron pipe for corner.  
New BTs- A Fir, 14" dia. bears S.2°10'W., 10.7 ft.  
A Fir, 10" dia. bears S.70°36'W., 24.8 ft.

-----  
James W. Byron, Deputy Co. Surveyor - April-May 1957  
C.S. File 47/180.

-----  
Found - 1 1/4" I.P. at corner bent over by cat. Replaced with  
brass cap. The 14" Fir, S. 2°10'W., in good  
condition and shows good face-I do not open.  
The 10" Fir, S.70°36'W., down. Both BTs check  
for bearing & Distance.

(Cont. Next Page)

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 5; Sec. 32 T 28-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Lower section of charred post as set by Cole, same location as 1 1/4" I.P.  
Set - Iron Pipe with brass cap at corner point mkd:  
1/4 S <sup>32</sup>/<sub>5</sub> T28S, 4W County Surveyors Office  
New BT - 8" R.Fir, N.8°W., 23.2' mkd. T28S R4W 1/4S32 CSBT.

Found OK, May 1991 - R. Dolan, M 113-14.  
Fd. Ok by G. Lang, 1/2014 - M167-19  
Fd. BC by R. Brown, 12/2015 - 2015-0024A-B