

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6378)

Set ¼ sec. post at average distance, from which
A B.Oak 18" dia., bears N.67°W., 164 lks. dist.
A B.Oak 16" dia., bears S.55°W., 232 lks. dist.

GL0 survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6395)

¼ sec. cor. Set new post as per instructions. Old trees standing, viz:
A B.Oak 18" dia., bears N.67°W., 164 lks. dist.
A B.Oak 16" dia., bears S.55°W., 232 lks. dist.

W.H. Wood, Deputy Co. Surveyor - W.S. Crear, A.C. Redifer, crew - Wit: P.R. Weaver, G.M. Dyer, W.H. McClain and W.O. Suoffard - Nov. 3-6, 1925 - Vol. 3 Pg. 229

Old BT, N.67°W., 164 lks., OK. Other BT dead.
Marked new tree "¼ S16 CS" which is a 12" Red Fir S.74½°W., 10 lks.

A. Boyer, D.C.S. - Wit: Ted Shellabarger and Ralph Schrader - Oct. 18, 1938 - C.S. File 16/4 and M 3-67

This corner is just off N. of old fence line running East. Both BTs are dead.
Set Cedar post, set by Woods, back in place from stump of Fir BT and down Oak which Woods used in 1925. Marked new trees for BTs:
N.26½°E., 256.0 ft. Fir 16" dia.
S.50½°E., 314.3 ft. Alder 18" dia. on creek bank, bark blaze, a 9" and an 18" Alder against this tree.

John H. Markham, Jr. - For: Stomar Lbr. Co. - Aug/Dec. 1956 - C.S. File 42/188-2

At corner point, found scribed post set by C.S. in 1938. Drove a 2" x 30" solid steel shaft 22" in ground at corner point., from which
A 4" B.Oak bears S.4°E., 29.0 ft. mkd. ¼ S16 BT.
A 7" Laurel bears N.50°W., 57.0 ft. bark scribed ¼ S S9 T29S R4W BT.
A woven wire fence bears East and West from corner.
School Hollow Creek bears East 350.0 ft.

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - April 1963 - C.S. File 52/126-129

Found - Shaft at corner and both BTs as recorded by Markham. Rescribed - (Wood) 7" now 9" Laurel N.50°W., 57.0 ft. "¼ S9 CS BT".

BLM Resurvey by James E. Jelley and Lynn Roseberry Cadastral Surveyors under Group #'s 255; 701; 938 - Surveyed July/Oct 1977 (DCSO records Vol. 39 Page(s) 15885)

The ¼ sec. cor. of secs. 9 and 16, perpetuated and recorded by Wood, in 1925, from original evidence no longer in existence, and further perpetuated and recorded by Markham in 1956, monumented with a solid steel shaft, 2" dia., loosely set, projecting 15" above ground, alongside of which is a burned cedar post 2" x 4" sq., loosely set, projecting 16" above ground, with scribe marks S9 CS visible on N. face and S16 CS visible on S. face. This corner is accepted as the best available evidence of the original corner position, from which a bearing tree mkd. by Boyer in 1938:

A Fir 16" dia., bears N.24°E., 372 lks. dist. with healed blaze.

and bearing trees mkd. by Markham:

An Oak 10" dia., bears S.4°E., 44 lks. dist. with healed blaze.

A Madrone 10" dia., bears N.53°W., 86½ lks. dist. with scribe marks ¼ S9 CS BT visible on open blaze. This tree was rescribed by Byron in 1963.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, directly over steel shaft, with brass cap mkd: T 29 S R 4 W

¼ $\frac{S\ 9}{S\ 16}$
1969

from which a new bearing tree

A Fir 16" dia., bears S.14°W., 88 lks. dist. mkd. ¼ S16 BT
Deposit cedar post alongside iron post.

Survey by Bruce Shaner - For: Roseburg Forest Products - Aug. 1993 - C.S. Files 63/96 and 63/153-24, also RM 3-79

CONDITION REPORT ONLY

Found - 3¼" brass cap on a 2½" iron pipe.

20" D.Fir BT, face overgrown bears N.24°E., 245.5 ft

10" Oak BT, face overgrown, bears S.9°W. (Rec. S.4°E.) 29.0 ft. (BT now dead)

(Cont. Next Page)

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

16" Madrone BT, face overgrown, bears N.53°W., 57.1'
36" D.Fir BT, face overgrown, bears S.14°W., 58.1'
Corner on E-W fence line, about 1 chain West of dirt access road.

David Edwards - Crew: B. Miller & E. Sprinkle - 1/16/2015 - C.S. File 65/87-3

Found - Standard 1969 B.L.M. brass capped iron pipe.
30" dia. ± Fir stump N.24°E. 245.5' Markham's Oak is gone.
43" dia. ± Fir stump S.14°W., 58.1'
A 17" dia. Madrone with healed blaze bears N.53°W., 57.1'
New - A 9" diam. Fir scribed "¼ S9 BT" bears N.27°E., 21.0'
No suitable trees within limits in Section 16.
Set 6 ft steel post 2 ft East
Compass decl. 15°E.