

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34 only (South)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6359)

Set a post at proper distance, cor. of secs. 3, 4, 33 and 34, from which

- A B.Oak 18" dia., bears S.57°E., 42 lks. dist.
- A B.Oak 16" dia., bears N.85°E., 60 lks. dist.
- A B.Oak 10" dia., bears N.57°W., 38 lks. dist.
- A B.Oak 12" dia., bears S.40°W., 26 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 15 Page(s) 6403)

I find here a post in place, but not marked, evidently set by Deputy Byars in 1872; also a stump of a B.Oak in Sec. 33, which corresponds in size and direction with the one in this section, described in the field notes furnished me; (I run a line North from here 40 chs. in search of the ¼ post, but am unable to find any trace of post, bearing trees or any evidence of a line starting from here; neither has the line coming North from ¼ post between secs. 3 & 4 been closed upon here.)

I restore this corner by setting an Oak post 4½ ft. long, 4" sq., 24" in the ground, mkd: T29S R4W on N.; S34 on E.; S33 on W. faces, and 3 notches on E. and W. faces, from which

- A Fir 8" dia., bears N.30½°E., 37 lks. dist. mkd. T29S R4W S34 BT.
- A Fir 8" dia., bears N.63½°W., 11 lks. dist. mkd. T29S R4W S33 BT.

Survey by Fredrick E. Warner - For: J.H. Baxter & Co. - March/April 1957 - C.S. File 42/257

Found remains of decayed post.
Set an iron pipe at corner point 2" dia., 3 ft. long, 28" in ground, from which

- A D.Fir 30" dia., bears N.32°E., 24.42 ft. chopped with partial scribe marks.
- A D.Fir 26" dia., bears N.60°30'W., 7.26 ft. chopped and old scar visible.

George J. Wenderoth - April 1957 - M 5-30

Found 2" Iron pipe at corner point.
Marked new trees:
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 33 & 34 only, (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>16" Madrona N.42°42'E., 46.5 ft. 20" Fir N.72°42'W., 36.8 ft.</p>
<p>Survey by Marvin Ramsey - April 1959 - C.S. File 51/19 ----- Monumented with an iron pipe 2" dia., 8" above the ground and marked RS298, from which the original BTs: 30" D.Fir bears N.32°E., 37 lks. dist. 26" D.Fir bears N.60½°W., 11 lks. dist.</p>
<p>James W. Byron, Deputy Co. Surveyor - Mike Darby; Wm. Stoffel crew - May 1963 - C.S. File 52/126-139 ----- Found - 2" I.P. at corner 16" Laurel N.42°E., 46.5 ft. down, shows scribing. 20" Fir N.72°W., 36.2 ft. shows scribing. New BT - 9" Laurel bears N.48°E., 41.8 ft. scribed S34 T29S R4W CS BT.</p>
<p>Fd. OK, Oct. 1992 by G. Lang - M 117-1</p>
<p>BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20092-3) ----- The cor. of secs. 33 & 34 perpetuated by Warner, in 1957, further perpetuated by Wenderoth, in 1957, further perpetuated by Ramsey, in 1959, further perpetuated by Byron, in 1963; monumented with an iron pipe, 2" diam., firmly set, projecting 6" above ground from which the remains of the OBTs A fir, 39" diam., bears N.30½°E., 37 lks., w/healed blaze. A fir, 28" diam., bears N.63½°W., 11 lks., w/healed blaze. and a remaining bearing tree mkd. by Wenderoth A fir, 27" diam., bears N.70½°W., 56 lks., w/healed blaze. and the remains of a bearing tree mkd. by Byron A madrone snag, 11" diam., bears N.48 3/4°E., 62 lks., w/scribe mks 29S R4W S34 CSBT vis on open double blazes At the corner point Set a stainless steel post, 28" long, 2½" diam., 24" in the ground, directly over the iron pipe, with brass cap mkd. T29S R4W S 33 S 34 ----- S 4 T30S R4W 1994 Deposit a white "DEEP-1" magnetic marker at base of stainless steel post. continued next page</p>

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. Ok by Ken Hoffine, July 2005 - M148-23

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 4/4/2005 - C.S. File 67/10-38

Condition report only:

Found - 3" brass cap on 2½" dia., pipe projects 4" above
ground. (Properly marked)
39" dia., D.Fir now 40"x4' tall stump. Chopped out
blaze visible.
11" madrone noted as snag by BLM in 1994 is an alive
tree, scribing still visible.
All other accessories are found as noted in BLM 1994
report.
Decl. 16¾°E.