

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by Bruce Shaner - For: Roseburg Forest Products - Aug. 1993 - C.S. Files 63/96; 63/153-25 and RM 3-79

CONDITION REPORT ONLY

Found - 3¼" brass cap on a 2½" iron pipe, from which
24" D.Fir BTR, face overgrown, bears N.62°E., 66.7
ft.

24" Cedar BT, face overgrown, bears S.20°W., 100.9
ft. (Rec. 75.2 ft.)

Corner located on new N-S fence line.

BLM resurvey by George M. Winter, Cadastral Surveyor, under Group No. 2747, surveyed May/July 2014 - (DCSO records Vol. 58 page(s) 23200)

The ¼ sec. cor. of secs. 15 & 16, monumented with an iron post, 2½" dia, firmly set, projecting 8" above ground, with brass cap (properly) mkd.

from which BTs mkd. by Roseberry and Jelley in 1967-77

A fir, 27" dia, bears N.62°E., 66.7 ft., with a healed blaze.

A cedar, 31" dia, bears S.20°W., 100.9 ft., with a healed blaze. (Record, 75.2 ft.)

Corner is located under a wire fence extending N. and S.

From this cor., a point established as the ¼ sec. cor. of secs. 15 & 16 by Markham, in 1964, bears S.80°49'E., 52.5 ft., monumented with a truck axle, 1" dia., projecting 2" above ground, bent to the south, and is not accepted as the cor. and not utilized in the course of this survey.