

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Cor. to Secs. 3 & 4; 34 & 33 T 28-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, Contract # 44 dated May 30, 1854.
(DCSO records Volume 13, Pg. 5607)

Set a post at proper distance from which:
A R.Fir, 4" dia. bears S.80°E., 32 lks. dist.
A R.Fir, 4" dia. bears N.31°E., 24 lks. dist.
A R.Fir, 6" dia. bears N.55°W., 36 lks. dist.
An Alder, 18" dia. bears S.35°W., 29 lks. dist.

South Boundary of T.28-4, surveyed by W.H. Byars, Contract # 376 dated Jan. 22, 1881. (DCSO recs. Vol. 13 Pg. 5613-14)


Set Fir post for sec. cor. from which:
A Maple, 12" dia. bears N.80°E., 1.25 chs. dist.
A Fir, 24" dia. bears S.63°E., 83 lks. dist.
A Fir, 7" dia. bears S.35°W., 50 lks. dist.
A Fir, 20" dia. bears N.38°W., 40 lks. dist.
Note: Per note in Byars 1881 survey "In the execution of this work I found that the old line established for the S bdy of this Township was glaringly at fault..." Byars set his own corners See CS 63/166 BLM opinion file T28-4 (added 4/7/2010)

G.G. Stewart, Deputy Co. Surveyor. Witnesses: C. Crocker, F. Evans. Jan. 30, 1922 - M 2-4 & Vol. 3, Pg. 113.

Found - A scribed stake: all BTs gone except Maple stump at N.80°E., 1.25 chs.
Set an Iron Pipe for corner.
New BTs - A Fir, 30" dia. bears S.34°E., 47.0' dist.
A Fir, 48" dia. bears S.68°W., 17.0' dist.

James W. Byron, Deputy Co. Surveyor, & Dale McFarland, Jim Powell - August 1961 - C.S. File No. 49/67-21

Found - 3/4" I.P. at corner & both BTs. as recorded by Stewart, 1922. S.E. BT now down, shows scribe marks. S.W. BT shows good scar. Old board fence at Corner thus:



-o- sec. cor.
Set Brass Cap alongside Cor. pipe & mkd: Co. Surveyor's Office 1961.

S 33 | S34 T28S R4W
S 4 | S 3 T29S R4W

New BTs -R.Fir, 20" dia. bears S.51½°E., 30.2 ft. scribed-S3 T29S R4W CS BT.

(Cont. Next Page)

