

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec Cor for 34 and 35 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6359-60)

-----  
Set a post at proper distance, cor. of secs. 2, 3, 34 and 35, from which

- A B.Oak 10" dia., bears S.57°E., 32 lks. dist.
- A B.Oak 6" dia., bears N.18°E., 60 lks. dist.
- A B.Oak 16" dia., bears N.57°W., 38 lks. dist.
- A B.Oak 8" dia., bears S.40°W., 28 lks. dist.

GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 15 Page(s) 6401)

-----  
The post set for this corner is gone but all the bearing trees described in the field notes of original survey are standing. I restore this cor. by setting a Cedar post 4½ ft. long, 4" sq., 24" in the ground mkd: T29S R4W on N. face; S35 on E. face; S34 on W. face; and 2 notches on E. and 4 notches on W. faces, from which

- A B.Oak 18" dia., bears N.80°E., 60 lks. dist. mkd. T29S R4W S35 BT.
- A B.Oak 12" dia., bears N.57°W., 38 lks. dist. mkd. T29S R4W S34 BT. This is the old bearing tree in Sec. 34, which I remark, as the old marks are overgrown.

Survey by John H. Markham, Jr. - Wit: Dennis Vaughn and Geo. Vaughn - Nov. 2, 1951 - C.S. File 40/386-3

-----  
Determined by Orig. BT.

- A B.Oak 14" dia., bears S.41°W., 18.5 ft. (OBT)
  - A B.Oak stump bears S.57°E., 25.0 ft. (OBT)
  - A B.Oak 16" dia., bears N.86°E., 36.0 ft. (OBT)
- At corner point, Set 1" x 30" I.P., from which
- A Laurel 8" dia., bears N.42°W., 12.0 ft. mkd. S34 2880 BT
  - A Pine 8" dia., bears N.41°E., 25.0 ft. mkd. S35 13 T.

Douglas Co. Surveyors Office - James W. Byron, Deputy - May 1956 - C.S. File 47/101 and RM 1-8

-----  
Found - 1" Iron pipe at corner.  
16" Oak BT, N.86°E., 36 ft. in good condition.  
8" Laurel N.42°W., 12.0 ft., down.  
14" B.Oak, old BT, stump only.  
8" Pine N.50°E., 25 ft., in good condition.  
Scribed -12" R.Fir N.55°W., 31.2 ft. mkd. T29S R4W CS BT.

(Cont. Next Page)

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec Cor for 34 and 35 only, (South)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - May 1963 - C.S. File 52/126-136

-----  
Found - 1" I.P. at corner.  
10" Pine N.50°E., 25.0 ft., shows scribing.  
Fir BT to NW., now stump.  
New BT - 13" Laurel N.33°W. 62.2' scribed S35 T29S R4W CS BT

Fd. OK Oct. 1992 by G. Lang - M 117-1  
Fd. OK, March 1996 by Ron Quimby - M 123-58

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCS0 records Vol. 52 Page(s) 20090-1)

-----  
The cor. of secs. 34 & 35 perpetuated by Markham, further perpetuated by Byron, in 1956, further perpetuated by Byron, in 1963, bears S.86°40'10" E., 40.174 chs.; monumented with an iron pipe, 1¼" diam., firmly set, projecting 8" above ground, from which the remains of the original bearing trees:

A root hole, bears N.86°E., 52 lks., with oak trunk, 23" diam, laying alongside, no marks visible. (Record, N.80°E., 60 lks.)  
A root hole, bears S.47½°E., 40 lks., with oak stump alongside, no marks visible. (Record, S.57°E., 32 lks.)  
An oak, 14" diam., bears S.43 ¾°W., 26 lks. no marks visible on decayed blaze. (Record, S.40°W., 28 lks.)  
and the remains of a bearing tree mkd. by Markham  
A pine snag, 22" diam., bears N.49 ¾°E., 35½ lks., with healed double blazes.  
and a bearing tree mkd. by Byron in 1956  
A root hole, bears N.54 ¾°W., 48 lks., with fir trunk, 12" diam., laying alongside, no marks visible.  
and a bearing tree mkd. by Byron in 1963  
A madrone, 13" diam., bears N.32 ¾°W., 94 lks., with scribe marks S34 BT visible on partially healed blaze.

At the corner point  
Set a stainless steel post, 28" long, 2½" diam., 24" in the ground, directly over the iron pipe, with brass cap mkd.

T29S R4W  
S 34 | S 35  
S 3  
T30S R4W  
1994

from which a new bearing tree  
A fir, 22" diam., bears N.80°E., 35½ lks., mkd. T29S R4W  
S35 BT. cont.

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec Cor for 34 and 35 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2777, surveyed June/July 2015/- (DCSO records Vol. 58 Page 23509-10)

-----  
The cor. of secs. 34 & 35 only, on the S. bdy. of T29S R4W monumented with a stainless steel post, 2½" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd. from which the remains of the original BTs reported by Seibold and Browning in 1993-95

A root hole bears N.86°E., 34.3 ft., with fallen oak trunk, 23" dia., lying alongside, with no marks visible.

An oak, 15" dia., bears S.43¾°W., 17.2 ft., with no marks visible on a decayed blaze.

and the remains of the BTs mkd. by Markham, in 1951, reported by Seibold and Browning

A root hole bears N.49¾°E., 23.4 ft., with fallen pine trunk, 22" dia., lying alongside, with a healed double blaze.

and the remains of the BT mkd. by Byron, in 1963, reported by Seibold and Browning

A dead and standing madrone, 13" dia., bears N.32¾°W., 62.0 ft., with fragmentary scribe marks visible on a partially healed blaze.

and the remains of the BT mkd. by Seibold and Browning

A root hole bears N.80°E., 23.4 ft., with fallen fir trunk, 24" dia., lying alongside, with a healed blaze.

and new bearing trees

A cedar, 10" dia., bears N.8½°E., 33.8 ft., mkd. X BT.

A cedar, 8" dia., bears N.73¾°E., 24.4 ft., mkd. T29S R4W S35 BT.

David Edwards - For: Schuyler & Hannigan - 10/2023 - M182-80

-----  
Fd. per record

Set 5.5' steel post east 2 ft on line.