

PRIMARY CORNER DESCRIPTION Sec Cor for 10, 11, 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6369)

Set a post cor. of secs. 10, 11, 14 and 15, from which
A B.Oak 8" dia., bears S.15°E., 130 lks. dist.
A B.Oak 15" dia., bears N.45°E., 209 lks. dist.
A B.Oak 8" dia., bears S.80°W., 450 lks. dist.
A B.Oak 8" dia., bears N.20°W., 440 lks. dist.

Cor. trees found standing in GLO survey by W.H. Byars, Contract #376, dated Jan. 22, 1881 (DCSO records, Vol. 15 Page 6391)

W.H. Wood - Crew, Geo. Spaur; A.C. Redifer - Wit: W.E. Hollinger; Elmer Heath; Ralph Smith - Aug. 29, 1925 - C.S. File 3/27; Vol. 3 Pg. 234 (and "old" corner book Pg. 123)

Set Oak stake scribed S10-11-14-15.
Marked:
S.61°30'W., 38 lks. Red Fir 15" "S15 CS".
S.10°00'E., 20 lks. Red Fir 15" "S14 CS"
N.26°00'W., 48 lks. Red Fir 15" "S10 CS".
N.45°00'E., 209 lks. B.Oak 18" (Old BT)

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - April 1963 - C.S. File 52/126-122

Found - Old BT, 15" now 21" Fir, S.10°E., 13.2 ft., cut into and fond scribing.
Old BT, 15" Fir, now snag N.26°W., 31.7 ft. Found good scar.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 4 W
S 10 | S 11
S 15 | S 14
1963

New BTs -9" Cedar N.74°E., 42.4 ft. scribed T29S R4W S11 CSBT
13" Fir S.69°W., 34.2 ft. scribed T29S R4W S15 CS BT
10" Cedar N.48°W., 46.0 ft. scribed S10 CS BT.

Fd. OK, June 1983 by Wm. Ruppert - M 94-61

continued next page

PRIMARY CORNER DESCRIPTION Sec Cor for 10, 11, 14 and 15

Alias	Description

BLM dependent resurvey by Wayne L. Rogers, Dale T. Bedell, Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Surveying Technician, under Group #1625 surveyed Sept. 1991 thru April 1993 - (DCSO records Vol. 52 Page(s) 19785-6)

The cor. of secs. 10, 11, 14, & 15, perpetuated by Wood, Deputy County Surveyor, in 1925, from original evidence no longer in existence, further perpetuated by Byron, Deputy County Surveyor, in 1963, bears N.87°38'00"W., 40.210 chs. dist.; monumented with an iron post, 1¼" diam., firmly set, projecting 12" above ground, with properly marked brass cap from which the remains of a bearing tree mkd. by Wood

A sawed fir stump, 21" diam., bears S.10°E., 22 lks., with fragmentary scribe marks visible on open blaze.

and the remains of bearing trees mkd. by Byron

A cedar, 21" diam., bears N.74°E., 63 lks., with healed double blaze.

A fir stump, 21" diam., bears S.70°W., 50 lks., with down log alongside with a healed double blaze.

A cedar, 26" diam., bears N.48°W., 68 lks., with a healed double blaze.

and new bearing trees

A fir, 6" diam., bears S.59½°E., 11 lks., mkd. T29S R4W S14 BT.

A fir, 4" diam., bears S.87¼°W., 17½ lks., mkd. X BT.

Found by R. Ward, Jan. 2002 only 2 bearing trees remaining due to road construction - See M139-35

BLM resurvey by George M. Winter, Cadastral Surveyor, under Group No. 2747, surveyed May/July 2014 - (DCSO records Vol. 58 page(s) 23198-9)

The cor. of secs. 10, 11, 14, & 15, monumented with an iron post, 1¼" dia, firmly set, projecting 13" above ground, with brass cap (properly) mkd.

from which the remaining BT mkd. by Byron, in 1963

A cedar, 24" dia, bears N.74°E., 41.6 ft., with a healed blaze.

and a bearing tree mkd. by Rogers, et al., in 1991-93

A fir, 11" dia, bears S.59½°E., 7.3 ft., with a healed blaze.

and new bearing trees

A fir, 5" dia, bears S.76¾°W., 81.7 ft., mkd. X BT.

A fir, 5" dia, bears N.64°W., 42.4 ft., mkd. X BT.

Corner is located on the N. side of a wood fencepost, with wire fence extending S.