

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Pg(s) 6390)

Set Hemlock post for the ¼ sec. cor., from which
 A Hemlock 18" dia., bears N.20°W., 22 lks. dist.
 A Fir 10" dia., bears S.28°E., 41 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - M. Godfrey; S. Bilow, crew - Feb. 26, 1958 - C.S. File 49/67-1

Found - Orig. 10" now down and partly rotted Fir snag.
 Section at base shows good scribing "BT".
 Orig. NW. BT gone.
Set Brass cap at cor. mkd: County Surveyors Office
 T 29 S R 4 W
 ¼ S2|S1
 1958
New BTs -20" Hemlock bears S.33°W., 26.5 ft. scribed ¼ S2 CS
 BT.
 36" Cedar bears N.5°E., 21.0 ft. scribed ¼ S1 CS BT.

Fd. OK, Oct. 1981 by B. Shaner - RM 3-54

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, under Group No. 2300: Admin. file #0602, surveyed May/June 2006 - (DCSO recs Vol. 56 Pg 22315 & Plat T29-4 2011-3)

The ¼ sec. cor. of secs. 1 & 2, remonumented Byron in 1958 monumented with an iron post, 1¼" dia., firmly set, projecting 15" above ground, with brass cap (properly) mkd. from which the remains of an orig. BT
 A roothole bears S.28°E., 27.1 ft. with decayed fir trunk, size indeterminate lying alongside with no mks visible. and BTs mkd. by Byron
 A cedar, 44" dia., bears N.5½°E., 20.9 ft. with axe marks visible on a partially healed blaze.
 A fir, 41" dia., bears S.33°W., 26.7 ft w/a healed blaze

Ken Hoffine - For: Lone Rock Timber Co. - Feb. 2011 - M157-39

Found - 1958 county cap 1.4 feet above ground.
 48" cedar bears N.5°E., 20.4 ft (record N.5°E., 21.0 ft) rotten face and tag
 43" W.Fir bears S.32¼°W., 26.0 ft (record hemlock S.33°W., 26.5 ft) healed face and tag corner lies on NW slope approximately 50 ft from main draw.