

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 36 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6361)</p> <p>-----</p> <p>Set ¼ sec. post at proper distance, from which A B.Oak 16" dia., bears S.35°E., 15 lks. dist. A W.Oak 12" dia., bears N.55°E., 60 lks. dist.</p>
<p>GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 15 Page(s) 6400) and (Vol. 17 Pages 7040-41)</p> <p>-----</p> <p>¼ sec. cor. post is gone, but both bearing trees are standing. I restore this corner by setting a Cedar post, 3 ft. long, 3" sq., 24" in the ground, mkd. ¼ S on N. face, from which A B.Oak 24" dia., bears S.35°E., 15 lks. dist. mkd. ¼ S BT A W.Oak 15" dia., bears N.55°E., 60 lks. dist. mkd. ¼ S BT</p>
<p>F.C. Frear, Deputy Co. Surveyor - Wit: A. Wallenburg; R. Morrison - Oct/Nov. 1918 - Field book 14=45; C.S. File 7/18; Vol. 3 Pg. 29-30; M 103</p> <p>-----</p> <p>Set 1½" x 36" I.Pipe, as per govt. BTs.</p>
<p>Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - May 1963 - C.S. File 52/126-134</p> <p>-----</p> <p>Found - 1" I.Pipe at corner 19.8 ft. East of cor. for 2 & 1, T30-4. Original BTs are same BTs as for Secs. 2 and 1. New BT - 7" Laurel bears N.3°E., 24.9 ft. scribed ¼ S36 CSBT.</p>
<p>Ron Rice, Ward NW Inc. - For: Seneca Jones Timber Co. - June 2003 - M142-46</p> <p>-----</p> <p>Found - 1¼" Iron pipe. Orig. BTs missing Sec. cor. common to secs. 1, 2 T30S R4W WM marked by a 1¼" bent iron pipe bears S.89°06'25"W., 19.47'. Set - "T" post adjacent to both pipes.</p>
<p>Fd. Ok by David Edwards - Jan 2005 - M 147-18</p>
<p> </p>