

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6364)

Set a post at average dist., from which
A B.Oak 20" dia., bears N.30°W., 9 lks. dist.
A B.Oak 16" dia., bears S.10°W., 15 lks. dist.

M.B. Germond - Sept. 1908 - Field Book 19 Pgs. 41-42; M 1-33 Vol. 3 Pgs. 25-27; C.S. Files 5/5 and 6/23

Reestablished as follows: Set White Oak post 5" x 5" x 3 ft., from which
Red Cedar 5" bears S.44°30'W., 22.5 lks.
Red Fir 8" bears N.11°30'E., 24.0 lks.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey; Clete Putnam, crew - July 7, 1960 - C.S. 49/67-6

Found - Both of Frear's BTs, both check record bearing and distance and each shows good scribing.
The NE. BT, now stump and the SW. BT is OK.
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 4 W
1/4 S 13
S 24
1960

New BT - 12" R.Fir bears N.24°W., 18.7 ft. scribed 1/4 S13 CSBT Rescribed, now 7" Cedar S.44 1/2°W., 14.8 ft. "1/4 S24 CSBT"

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - March 1963 - C.S. File 52/126-98

Found - BC at corner & both BTs scribed in 1960, now down.
New BTs - 16" R.Fir bears N.59°W., 27.5 ft.
10" Cedar bears S.23°W., 49.2 ft. scribed 1/4 S24 CSBT

BLM Resurvey by James E. Jelley and Lynn Roseberry Cadastral Surveyors under Group #'s 255; 701; 938 - Surveyed July 1967/Oct 1977 (DCSO records Vol. 39 Page(s) 15866-67)

The 1/4 sec. cor., perpetuated and recorded by Germond in 1908 & again recorded by Frear in 1918, from OBTs which are no longer in existence, and further perpetuated and recorded by Byron in 1960. This cor. is accepted as the best available evidence of the original corner position, monumented with an iron post, 1 1/4" dia., firmly set, projecting 14" above ground with 1960 brass cap. **continued next page**

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of bearing trees mkd. in 1908
A root hole bears N.11½°E., 24 lks. dist., with a down Fir stump alongside, 15" dia., no marks visible.
A Cedar stump 7" dia., bears S.44½°W., 22½ lks. dist., with illegible scribe marks visible on partially healed blaze. (Rescribed ¼ S24 CS BT by Byron, in 1960)
and the remains of a bearing tree mkd. by Byron
A root hole bears N.24°W., 28½ lks. dist. with a down Fir alongside, 13" dia., with scribe marks ¼ S13 CS BT visible on open blaze.
and the remains of bearing trees mkd. by Byron in 1962
A Fir snag 15" dia., bears N.59°W., 41 lks. dist., with scribe marks ¼ S13 CS BT visible on open blaze.
A Cedar 10" dia., bears S.22½°W., 74½ lks. dist., with scribe marks ¼ S24 CS BT visible on partially healed blaze.
and a new bearing tree
A Cedar 42" dia., bears N.37°W., 95 lks. dist. mkd. ¼ S13 BT.
Corner is located at the cor. of wire fences extending S.11°W. and N.89°W.

Fd. & used on BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor & Robert H. Browning, Surveying Technician, under Group #1775, surveyed Aug./Sept.. 1995 - (DCSO records Vol. 52 Page(s) 19945)