

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 038020

PRIMARY CORNER DESCRIPTION NW Cor. Bean DLC #38

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original DLC survey by Burnett & Bowman under Contract date 1855. (D.L.C. Records Book, page 535)</p> <p>-----</p> <p>Set a post marked, from which; A W. Oak, 10" dia., bears S.40½°E., 18 lks.</p>
<p>Douglas Co. Surveyors Office - W.F. Briggs Co. Surveyor - Jan. 5, 1892 - Vol. 1 Pages 198-9 - FB 4 Pages 10-12 - "Old" Cor. Book Page 128</p> <p>-----</p> <p>Set - White Oak post 4" sq. 3½' long mkd: C.38 CS. White Oak, 18" dia., S.40 ¾°E., 50 lks. C.38 CS.</p>
<p>Douglas Co. Surveyors Office - James W. Byron, Deputy - Dale McFarland - John Powell - 3/62 - C.S. File 49/64-71</p> <p>-----</p> <p>Found - 2" I.P. 30" above ground at cor. & at base of old Oak stake. Also find now 34" W. Oak, S.40 ¾°E. 34.0' shows good scar.</p> <p>New BT - 10" W. Oak bears N.6°W. 12.3' scribed NW CL 38 CS BT Note - Fence 70' East.</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 1/8/2009 - C.S. File 67/28-4</p> <p>-----</p> <p>Found - Broken off 2" O.D. iron pipe 10" below ground, source unknown. 18" dia., W.Oak now root hole bears S.40¾°E., 34.0 ft. (agrees w/rec) 1892 ¾" bent iron rod bent 0.6 ft. westerly protrudes 1" out of ground bears N.88°W., 39.5 ft. (Rec. West 39.09 ft. M33-63 1969 No evidence of 1962 DCS0 BT or Fence line found.</p> <p>New - 5/8"x30" long iron rod with DCS0 alum cap is set plumb in the center of fd. iron pipe, protruded 5" out of ground. MKD: DOUGLAS CO. NW 38 2009 SURVEYOR</p> <p>41" W.Oak, double blazed & scribed "NW DLC 38 CS BT" bears S.82°W., 278.3 ft. 34" W.Oak, double blazed & scribed "NW DLC 38 CS BT" bears N.6½°E., 245.3 ft.</p>