

PRIMARY CORNER DESCRIPTION NW Cor. Ireland DLC #47

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original DLC survey by Burnett & Bowman under Contract date 1855. (D.L.C. Records Book, page(s) 554)</p> <p>-----</p> <p>Set post marked as per instructions from which; A Black Oak, 15" dia., bears S.25°E., 361 lks.</p>
<p>Geo. Baker - 2/15/47 - C.S. File 40/5</p> <p>-----</p> <p>Found - Old witness tree 30" Black Oak, S.25°E., 283.26'. Set - 3/4" Gal. I.P. with mound of rock. New BT - 26" White Oak, N.46°48'W., 42.1'.</p>
<p>Douglas Co. Surveyors Office - James W. Byron, Deputy - Ray Irving - Dec. 11, 1953 - C.S. File 45/231</p> <p>-----</p> <p>Old BT N.46°48'W., 42.1' has been cut. Stump scribed BT visible - we did not look for other BT which was B. Oak S.25°E., 238.26'. Blazed & scribed 2 new BTs 18" Oak, mkd: C.L. #47 NW CS BT N.17°W., 79.3' 20" B. Oak, N.60°W., 74.0' mkd: NW Cl 47 CS BT Mag. Var. 21¼°</p>
<p>FD a 3/4" I.P. By G. Grubb - Dec. 1981 - RM 3-52</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 1/9/2001 - C.S. File 66/19-5</p> <p>-----</p> <p>Found - 3/4" I.D. iron pipe protrudes 1" out of ground (1947) Corner lies 26 ft. east of a N-S fence line. OBT not found. 26" now 18" dia., 2½ ft. rotted Oak stump bears N.46 3/4°W., 42.1 ft. (1947) 18" now 25" dia., W.Oak with a fully healed single blaze, bears N.17°W., 79.3 ft. (1953) 20" now 29" dia., B.Oak with a fully healed single blaze bears N.60°W., 74.0 ft. (1953) New - 12" dia., W.Oak double blazed & scribed "NW DLC 47 CS BT" bears S.25°E., 35.6 ft. Set mound of stone around base of Fd. IP. Compass decl. 17 3/4°E</p>
<p>Fd. Ok by Ed Farr, 12/2005 - 2006-0006</p>