

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 33 only.

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6425)</p> <p>-----</p> <p>Set ¼ sec. post at proper distance, from which A W. Oak, 10" dia., bears S.31°W., 32 lks. A W. Oak, 12" dia., bears N.67°E., 39 lks.</p>												
<p>G.L.O. Survey by Oscar F. Thiel, under Contract #658 dated May 21, 1896. (DCSO records Vol. 17 Page 7181)</p> <p>-----</p> <p>Junction of 4 fences, begin ascent and enter oak timber. I made a careful search in this vicinity for the ¼ Sec. cor., but could not find any trace of cor. post or witness trees, some stumps are left West of this point. At the supposed ¼ sec. cor. bet. secs. 4 & 33.</p>												
<p>Doug. County Surveyors Office - James W. Byron, Co. Surveyor - John Powell & Crew - 3/1970 - C.S. File 54/108 - M 39-45</p> <p>-----</p> <p>This corner set from survey at prorated distance. Set - Brass cap at Cor. Mkd:</p> <table style="margin-left: 100px;"> <tr> <td>County Surveyor's</td> <td>T 29 S</td> <td>R 5 W</td> </tr> <tr> <td>Office</td> <td>¼ S</td> <td>33</td> </tr> <tr> <td>1970</td> <td>T 30 S</td> <td></td> </tr> </table> <p>New BT's - 14" W. Oak, N.65°E., 85.5' mkd: "¼ S33 CS BT" 18" B. Oak, N.12°W., 129.0' mkd: "¼ S33 CKS BT" This Corner lies 6.0' N of E-W fence line & 140.0' S of ravine</p>	County Surveyor's	T 29 S	R 5 W	Office	¼ S	33	1970	T 30 S				
County Surveyor's	T 29 S	R 5 W										
Office	¼ S	33										
1970	T 30 S											
<p>Found OK by William Ruppert - July 1991 - M 112-32. Found OK by William Ruppert, Sept. 1992, M 115-70</p>												
<p>Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 2/7/2008 - C.S. File 67/25-8</p> <p>-----</p> <p>Found - 2½" dia., BC (properly mkd) on 1¼" O.D. iron pipe. BC/IP had been disturbed & leaned 0.8' westerly. All accessories missing due to excavation of new Subdivision lots to north.</p> <p>New - Dug down & located plumb position of BC/IP, referenced this position, removed & reset BC/IP at referenced position. Stamped "RESET 2008" on BC. (MKD) COUNTY SURVEYORS OFFICE</p> <table style="margin-left: 100px;"> <tr> <td>T29S</td> <td>R5W</td> </tr> <tr> <td>¼ S</td> <td>.33</td> </tr> <tr> <td>RESET</td> <td></td> </tr> <tr> <td>2008</td> <td></td> </tr> <tr> <td>T30S</td> <td></td> </tr> <tr> <td>1970</td> <td></td> </tr> </table> <p style="text-align: right;">cont. next pg</p>	T29S	R5W	¼ S	.33	RESET		2008		T30S		1970	
T29S	R5W											
¼ S	.33											
RESET												
2008												
T30S												
1970												

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 33 only.

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

12" dia., W.Oak, double blazed & scribed "¼ S33 CS
BT" bears S.82¼°E., 30.0 ft.
Brass cap at N¼ cor. sec. 4 only bears Easterly
97.87 ft. See M39-45
No other accessories were created at this time.
BC/IP is shown on Village View Subd. Ph. 2
(unrecorded at this time) and will have direct
ties to other property corners in subd.
Compass decl. 16¼°E.