

PRIMARY CORNER DESCRIPTION North ¼ Cor. Sec. 4 T30-5 only.

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6425)

-----  
Set 1/4 sec. post at proper distance, from which  
A W. Oak, 10" dia., bears S.31°W., 32 lks.  
A W. Oak, 12" dia., bears N.67°E., 39 lks.

G.L.O. Survey by Oscar F. Thiel, under Contract #658 dated May 21, 1896. (DCSO records, Vol. 17 Page 7181)

-----  
Junction of 4 fences, begin ascent and enter oak timber. I made a careful search in this vicinity for the ¼ Sec. cor., but could not find any trace of cor. post or witness trees, some stumps are left West of this point.  
At the Supposed ¼ sec. cor. bet. secs. 4 & 33.

Doug. County Surveyors Office - James W. Byron, Co. Surveyor - John M. Powell & Crew - March, 1970 - C.S. File 54/108 - M 39-45.

-----  
This corner set from survey at prorated distance:  
Set - Brass cap st Cor. Mkd:  
County Surveyor's T 29 S  
Office, 1970 T 30 S R 5 W S 4  
New BTs -6" B. Oak, S.77½°W., 4.5' mkd: "¼ S 4 CS BT"  
13" Laurel, S.80°W., 42.3' mdk: "¼ S 4 CS BT"

Doug. County Surveyors Office - Stephen Flause - R.W. Smith -Sept. 5, 1986 - C.S. 62/376

-----  
Brass cap missing. Searched for, not found.  
Found - A 6" B. Oak now a 9" D.B.H. B. Oak with a fully healed single blaze, which is opened to reveal visible scribing "¼" bears S.77½°W., 4.5' (per rec.)  
A 13" Laurel now a 15" D.B.H. Madrone with a fully healed single blaze which is opened to reveal visible illegible scribing bears S.80°E., 42.3' (Rec. S.80°W., 42.3')  
Set - A distance-distance intersection from the found bearing trees indicates that bearing originally recorded to the laurel (madrone) was incorrect; this conclusion is corroborated by the bearing tree tag, found on the tree, which was marked in 1970, and which indicates a bearing of S.80°E. A new 2 3/8" dia. brass cap mkd "Douglas County

(Cont. Next Page)

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 343100

PRIMARY CORNER DESCRIPTION North 1/4 Cor. Sec. 4 T30-5 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

(cont.)

Surveyor's T29S R5W 1/4 S4 T30S R5W 1986 Office",  
on a 1 1/4" O.D. iron pipe 32" long is set 26" in  
the ground at the distance-distance intersection  
from the found bearing trees as explained above.

New BT - A 9" D.B.H. Madrone double blazed and scribed "1/4 S4  
CS BT" bears S.60 1/4°E., 76.4'.

Note - Monument lies approx. 4' North from an old east-west  
fence and approx. 550' east from the paved end of  
Clark St.

Fd. B.C., March 1990, Partition Plat 1990-0027  
Fd. OK, November 1991, Bill Ruppert, M 114-33  
Fd. Ok, July 1993, Bill Ruppert, 1993-0050 A & B

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause  
- 2/7/2008 - C.S. File 67/25-9

-----  
Fd Ok as per DCSO 1986 renewal. All three BTs of record  
intact. Brass cap at S 1/4 Sec. 33 only bears Westerly 97.87 ft.