

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec. Cor. 3 & 4; 33 & 34, T28-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 13 Page 5651)

Set post corner to secs. 33, 34, 3 and 4, from which
A Y.oak 20" dia., bears S.72°W., 73 lks. dist.
A Y.oak 14" dia., bears N.70°W., 64 lks. dist.
A W.oak 28" dia., bears N.12°E., 74 lks. dist.
A W.oak 20" dia., bears S.49°E., 158 lks. dist.

Doug. County Surveyors Office - G.G. Stewart, DCS; S.D. Whitsett; W.S. Greer - June, 1922 - Vol. 3 Page 123; C.S. File 6/20

Found stumps of OBTs and some badly decayed.
Set Iron Pipe and marked:
18" Fir S.28½°E., 20.0 ft.
16" Fir S.63½°W., 6.2 ft.
16" Fir N.38°E., 6.7 ft.
16" Fir N.40°W., 41.1 ft.

Doug. County Surveyors Office - James W. Byron, Deputy - Dale McFarland, John Powell - Sept/Oct. 1961 - C.S. 49/64-11

Found - 3/4" I.P. at corner.
16" now 24" Fir snag, N.38°E., 6.7 ft., shows good scars.
16" now 28" Fir, N.40°W., 41.1 ft., shows good scars.
18" now 24" Fir snag S.28½°E., 20.0 ft., shows scars.
SW BT now fence corner and may die. (in 1961 fire area)
Set Brass cap mkd: County Surveyors S33|S34 T28S
Office, 1961 S 4|S 3 T29S R5W
New BTs -12" R.Fir bears S.78°W., 39.2 ft. scribed S4 T29S
R5W CS BT.
16" R.Fir bears N.8°E., 57.3 ft. scribed S34 T28S
R5W CS BT.
No live trees near to SE.

Found DCSO cap and 5 references. Corner is located on a SW slope, 16 lks. NWE of the corner of fences extending E., W. and N.
BLM Cadastral survey by Dale Bedell & Boyd Peterson, under Group # 1425, Survey April 1988/April 1990 (DCSO records, Vol. 49 Pages 18693-94)

(Cont. Next Page)

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec. Cor. 3 & 4; 33 & 34 T28-5

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Mark Smalley, L.S. #2354 - For: Roseburg Forest Products Co.
- July/Sept. 1993 - M 119-2

Found - 1961 County Surveyor BCIP
16" Fir, N.40°W., 41.1', stump
16" Fir, N.38°E., 6.7', rotten stump
16" Fir, N.8°E., 57.3', down
18" Fir, S.29°E., 20.0', stump
12" Fir, S.78°W., 39.2', healed
New BTs- 28" Cedar, S.86°E., 181.8' "S 34 BT"
6" Cedar, N.14°W., 106.5' "S 33 BT"
12" Madrone, North 133.8' "S 33 BT"