



TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor. Secs 26, 27, 34, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Note - Set 3/4" I.R. at Fence Corner, N.52°E., 176.0' from brass cap. See C.S. File 49/139 for sketch.</p>
<p>Fd B.C. - 7/91 - By W. Ruppert - M 112-32 Fd. OK by D.Bentz, July 1995 - M124-5</p>
<p>Douglas County Surveyors Office - Randall Smith &amp; Stephen Flause - Apr. 2, 1997 - C.S. 64/74-9</p> <p>-----</p> <p>Mon. Fd. - 2½" Brass cap on a 1½" O.D. iron pipe 3" below ground I.P. is bent 4" North of plumb.</p> <p>Accessories Fd. - No OBT's Found 3/4" I.R., bears S.78 3/4°E., 111.1' on north bank of myrtle creek (rec. S.78°50"E., 109.7' on south bank of myrtle creek) 1955. No other accessories from 1955 renewal found. 20" now 33" dia. W.Oak, with a fully healed single blaze facing BC/IP and a previously opened unhealed hole facing northwesterly, bears S.71°E., 124' (agrees with rec.) 1963. 3/4" I.R. from 1963 renewal not found.</p> <p>Mon. Set - BC/IP straightened and returned to plumb position measured 36" long. set 2" below ground.</p> <p>New Accessories - 12" dia. Maple, double blazed and scribed "T29S R5W S34 CS BT", bears S.15½°W., 102.1' (Note tree has fence wire grown into trunk.) 4" dia. Myrtle, double blazed and scribed "X BT", bears S.14°E, 75.4'.</p> <p>Corner lies approx 18' northerly of paved golf cart path. A 38" Oak, S.75°W., 260.14' from BC/IP was checked for age by tree bore found to be fast growing not large enough to be OBT.</p>
<p>Fd. Ok by Ken Hoffine -May 2004 - M144-71 A&amp;B</p>
<p>BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2795, surveyed July/Aug. 2015- (DCSO records Vol. 59 Page 23575-6)</p> <p>-----</p> <p>The cor. of secs. 26, 27, 34, &amp; 35, reestablished at proportionate measurement by Johnson, in 1955, perpetuated by Byron, in 1963, and further perpetuated by the Douglas County Surveyor's Office in 1997; there is no remaining evidence of the original cor., and is accepted as a careful and faithful reestablishment of the cor., as documented in the report by continued next page</p>

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor. Secs 26, 27, 34, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

(cont.) Jeffery O. Covington, Cadastral Surveyor, dated August 24, monumented with an iron post, 2½" dia., firmly set, projecting 3" above ground (alongside of which is an iron rod, ¾" dia., firmly set, buried 10" below ground), with brass cap (properly) mkd.

from which the remaining accessory mkd. by Johnson

An iron rod, ¾" dia., firmly set, projecting 1" above ground, bears S.78°33'32"E., 111.14 ft., with no cap. and bearing tree mkd. by Byron

An oak, 35" dia., bears S.69¾°E., 123.5 ft., with a healed blaze.

and BTs mkd. by the Douglas County Surveyor's Office

A myrtle, 6" dia., bears S.14½°E., 75.4 ft., with a healed double blaze.

A maple, 15" dia., bears S.15¾°W., 102.3 ft., with a healed blaze.

From the section corner

E., 528 ft., to the South Fork of Myrtle Creek, 15 ft. wide, course S.80°W.

S., 128 ft., to the South Fork of Myrtle Creek, 15 ft. wide, course S.40°W.

W., 535 ft., to the South Fork of Myrtle Creek, 15 ft. wide, course N.78°W.