

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6434)

-----  
Set a post for cor. to secs., 10, 11, 14, & 15, from which,  
A B. Oak, 16" dia., bears S.15°E., 24 lks.  
A B. Oak, 18" dia., bears N.35°E., 14 lks.  
A B. Oak, 12" dia., bears S.23°W., 34 lks.  
A W. Oak, 14" dia., bears N.65°W., 37 lks.

H.L. Eppstein - H.L. McHenry - N.E. Richardson - Oct. 30, 1921 - "Old" Corner Book Page 126 - (Could find no record source)

-----  
I renewed this corner from old B.T.s I found two trees standing and two trees down. I set a 4"x4"x30" Yew Wood and marked new trees as follows:  
A 15" Fir bears N.14°W., 31 lks.  
A 15" B. Oak bears S.62°30'W., 50 lks.  
A 12" Fir bears N.80°E., 27 lks.  
A 8" Fir bears S.61°30'E., 20 lks.

Doug. County Surveyors Office - Ben B. Irving, Co. Surveyor - Witness: R. Carey - May 1945 - C.S. File # 38/28

-----  
Set 1"x48" Iron pipe 34" in ground.

Doug. County Surveyors Office - James W. Byron, Deputy - D. McFarland - J. Powell - Nov./Dec. 1961 - C.S. File 49/64

-----  
Found - 1"x48" I.P. at corner & stumps that check 1921 renewal for N.E. & N.W. BTs. We find stump hole that checks S.W. BT. Also find, Now 12" R. Fir, down, S.61½°E., 13.2'. We open & find good scribing "¼S" (1921 Renewal)  
Set - Brass cap alongside I.P. mkd:  
County Surveyor's S 10 | S 11 T29S R5W  
Office 1961 S 15 | S 14  
New BTS -20" R. Fir, bears N.11°W., 108.8' scribed S10 T29S R5W CS BT.  
15" R. Fir, bears N.69°E., 25.10' scribed S11 T29S R5W CS BT.  
No trees suitable near to South.

Doug. County Surveyors Office - James W. Byron, Co. Surveyor - John M. Powell & Crew - March 1969 - C.S. File 54/81

-----  
Found - 1961 County Surveyor's brass cap.  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

20" D. Fir, now stump, N.11°W., 108.8', burnt scribe visible.  
15" D. Fir, now stump, N.69°E., 25.1'.  
Set - 6' steel fence post alongside brass cap 5' above ground.  
New BT - 11" D. Fir, N.10°W., 130.5' scribed T29S R5W S10 CS BT.  
This corner lies 2.0' west of N-S fence line. No other trees available.

Doug. County Surveyors Office - Randall Smith, Deputy - Stephen Flause - June 6. 1990 - C.S. 64/9-9  
-----  
Fnd -A 1961 2½" dia., DCSO brass cap on a 1¼" O.D. iron pipe protruding 12" above ground.  
1" I.D. iron pipe is found along north side of BC/IP. 1" IP protrudes 20" above ground and is bent to the southeast.  
No original BTs found.  
15" now 18" dia., 2' high rotted and burnt D. fir stump no blaze or scribing visible, bears N.14°W., 21.4' (Rec. N.14°W., 20.5' possible face measurement)  
8" Fir now depression in ground bears S.61½°E., 13.2' (agrees with record)  
20" now rotted and burnt D. fir stump of indeterminate size, bears N.11°W., 108.8' (agrees with rec.)  
Northeast BT from 1961 renewal is gone.  
11" now 9" dia., 25' tall D. fir snag with a unhealed single blaze with scribing visible "T29S R5W S10 CS BT" bears N.10°W., 130.5' (agrees with record)  
New BTs -5" dia., madrone bark scribed "T29S R5W S15" CS BT bears S.22½°W., 5.6'.  
6" madrone bark scribed "T29S R5W S15 CS BT" S.83½°W., 17.0'.  
4" dia., madrone bark scribed "T29S R5W S14 CS BT" bears S.64°E., 13.5'.  
4" dia., D. fir double blazed and scribed "X BT" bears N.9°E., 41.6'  
Corner lies approx 2' west of a northerly-southerly fence line.