

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 040040

PRIMARY CORNER DESCRIPTION SE Cor. Clark DLC #40

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Original - Bowman and Burnett, under Contract dated Sept. 1855

Set a post marked as per instructions, from which
A W.Oak 8" dia., bears N.10°W., 212 lks.

Briggs, Feb. 6, 1886 - Vol. 1 Page 72

Set post to SE corner of Clarks don: by a W. Oak 24" dia.,
but no inscription thereon.

C.C. Gall, Resident Engineer, Oregon State Hwy Dept. Myrtle Creek, OR - March 11, 1955 - C.S. File 41/346

This corner falls inside of the State Highway right of way. Marked by a 12" x 14" x 14" triangular rock. The corner was not disturbed. The corner lies 110.0 ft. northeasterly of the highway right of way centerline and 5 ft. above the centerline of the pavement.
A 4" x 4" white wood guard post set by the corner and marked "D.L.C."
(Also see RM 1-79)

Fd. OK, by Don Garrett, August 1970, C.S. File 55/159
Fd. OK, by Bill Ruppert, July 1981, M 88-20

DCSO-GIS Corner visitation - 8/24/2004 - Typed: 2/1/2011 - C.S. File 67/33-1

Monument - stone
Comment - (needs) rehab

Fd. Ok by Neil Hibbs, 2/2006 - 2006-0031

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - Feb. 28, 2011 - C.S. File 67/33-14

Found - 12"x14"x14" pyramid shaped stone protruding 1' as fd in 1955 (Origin unknown) Stone is 140' NE'ly from conc. median and 5' above road surface of Interstate Hwy 5.
The OBT a W.Oak 8" dia, now a long dead rotted stump ≈ 30" dia. 2' tall, with very old searching hole; bears N.10°W., 139.9 (as per record)

continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 040040

PRIMARY CORNER DESCRIPTION SE Cor. Clark DLC #40

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

	<p>A $\frac{3}{4}$" I.D. IP that is protruding 1/2" (Info from M4-42) bears North 27.2 (record North 22.9) 3' easterly of R/W fence. Pipe may have been moved N. when R/W fence was built.</p> <p>A 4"x4" white wood guard post set north 2' north protruding 2.5 mkd "DLC Cor"</p> <p>New - Do to solid condition of stone we do not set a BC monument.</p> <p>An 11" DBH madrone marked "SE DLC 40 CS" "BT" on double blaze; bears S.22°E., 6.5 ft.</p> <p>A 12" DBH W.Oak mkd "SE DLC 40 CS" "BT" on a double blaze; bears N.16½°W., 11.8 ft.</p> <p>Note - Monument is on gentle east slope in remnant oak woodland with open pasture to east & I-5 to West. East 13.5 from stone to fence per sketch. Decl. 15¾°E</p>
--	---