

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Cor. Sec. of 30, 31; 25, 36 T29-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6456)

Set a post, from which:

- A Laurel, 5" diam., bears N.75°W., 8 lks.
- A Laurel, 7" diam., bears S.45°W., 18 lks.
- A Laurel, 7" diam., bears N.70°E., 5 lks.
- A B. Oak, 4" diam., bears S.18°E., 26 lks.

Re-establishment of corners - Fred Mensch U.S. Deputy Surveyor - under date of Dec. 4, 1905 (DCSO Vol. 15 Pg. 6505)

A red fir, 7" diam., for cor. of secs. I mark T29S S30 on NE. R6W S31 on SE. S36 on SW. and R7W S 25 on NW. side, with 5 notches on N. and 1 notch on S. edge, from which:

- A Laurel, 10" diam., bears N.33°E., 36 lks., mkd T29S R6W S30 BT.
- A Laurel, 16" diam., bears S.54°E., 59 lks., mkd T29S R6W S31 BT.
- A Laurel, 16" diam., bears S.15°W., 40 lks., mkd T29S R7W S36 BT.
- A Laurel, 8" dia bears N.49°W., 29 lks mkd T29S R7W S25 BT

Fd. Post at corner, GLO survey by Roy Campbell, under Contract #789, Aug. 1909 (DCSO records, Vol.15 Pg.6515)

Ben B. Irving, Deputy Co. Surveyor - Wit. N.E. Richardson, Frank Royer, Robinette, Bill Weightman - May 1934 - M 1-27 & C.S. 37/171

Original tree for corner in place but badly rotted. Original BT's as described in Government field notes
Set 4" x 4" x 36" fir post.

Arthur Boyer - Wit: Frank Smith, B.B. Lewis & Mr. Hollenback Apr. 24, 1952 - C.S. 41/24

Found the Laurel wit. tree which was orig. growing in sec. 36, T29-7. This tree was rooted out by a bulldozer and laying on the side of a newly graded road. Found the root hole for this tree and from there the approx. sec. cor. was located and then the only standing witness tree was found, the Laurel in Sec. 30 which was dead and about to fall. The sec. cor. was set from this tree and the following BTs were marked:

- 24" Fir, N.89°30'E., 18.5 ft., Trees mkd. sec. 30 Twp. 29S R6W. BT.
- 18" Fir, S.56°E., 73 ft., bark blaze, Trees mkd. sec. 31 Twp. 29S R6W., BT. (Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30, 31; 25 & 36, T29-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

18" Fir, N.27°30'W., 79 ft., bark blaze, Tree mkd. Sec. 25
T29S R7W BT 1581.
23" Fir stump, S.56°30'W., 75 Ft., mkd. sec. 36 T29S R7W
BT on root of stump just above ground surface.
The corner is about 15 ft. east of the new road.

Douglas Co. Surveyors Office - James Byron, Deputy - Wit.
S.A. Bilow - Apr 27, 1959 - C.S. 49/139-2

Found - Original 10", now 8" Laurel snag, shows good
scribing, "S 3 T29S BT" N.33°E. 23.8 ft.
Original SW BT down, dozed out of position, shows
good scribing "S36 T29S"
All BTs as recorded by Boyer, except NE BT., which is
now a snag.
No other trees near to N.E.
Set Brass Cap at corner & alongside squared & scribed Corner
Post. Mkd. Brass Cap: County Surveyors Office
R7W | R6W
S25 | S30
S36 | S31
1959
No new trees scribed.

BLM Resurvey - Wayne Roger, Cadastral Surveyor - Grp. # 1030
Aug/Sep 1980 - (DCSO Vol. 45 Pg. 17264)

Cor. on the W. bdy. of the Tp., perpetuated and recorded by
Arthur Boyer, in 1952, and further perpetuated and recorded
by James W. Byron, in 1959, monumented with an iron post 1¼"
diam., firmly set, projecting 12" above ground, with brass
cap mkd.: County Surveyors Office
T29S
R S25 | S30 R
7 S36 | S31 6
W 1959 W
From which the remains of the bearing trees mkd. by Mensch
A root hole, bears N.33°E., 36 lks., with a down madrone,
10" diam., alongside no marks visible
and bearing trees mkd. by Boyer
A fir snag, 25" diam., bears East, 29 lks., with scribed
mks. S30 T29S R6W S BT visible on bark
A fir, 23" diam., bears S.56°E., 109 lks., with scribe mks
S31 T29S R6W BT visible on bark
and new bearing trees
A fir, 8" diam., bears N.79°E., 48 1/2 lks., mkd. T29S R7W
S30 BT.
(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30, 31; & 25, 36, T29-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 8" diam., bears S.27°W., 37 lks., mkd. T29S R7W S36
BT.

A fir, 8" diam., bears N.63°W., 58 lks., mkd. T29S R7W S25
BT.

The corner is located in a fence corner, extending N. and W.

BLM rehabilitation of certain corners, Timothy J. Moore, Cadastral Surveyor & Robert H. Browning, Surveying Tech., under Group #2000, Surveyed July 2002, - (DCSO records Vol. 54 Page(s) 21140-1)

The cor. of secs. 25, 30, 31, & 36, on the east bdy. of the Tp., monumented with an iron pipe, 1¼" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd. from which the remains of BTs mkd. by the Douglas County Surveyors Office, in 1952

A fir snag, 26" dia., bears S.89½°W., 19.1 ft. with scribe marks S30 BT visible on bark. (Record, East)

A sawed fir stump, 28" dia., bears S.56°E., 71.9 ft., with scribe marks BT visible on bark.

and bearing trees mkd. by Rogers

A fir, 16" dia., bears N.79°E., 32.0 ft., with a healed blaze.

A fir, 11" dia., bears S.27°W., 24.4 ft., with a healed blaze.

A fir, 16" dia., bears N.63°W., 38.3 ft., with a healed blaze.

and a new bearing tree

A fir, 14" dia., bears S.77°E., 48.8 ft., mkd. T29S R6W S31 BT.

Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

Corner is located 1 ft south of a cor. of woven wire fences, which extend North and West.

The geographic position (NAD 1983 (CORS)) of this cor. as determined by NAVSTAR (GPS), utilizing dual frequency, carrier phase GPS receivers, (Trimble 5700), relative to the National Spatial Reference System, is as follows:

Latitude: 43°00'48.89"N., Longitude: 123°27'52.85"W.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2270, Surveyed May/Aug. 2009 - (DCSO records Vol. 57 Page(s) 22718-9)

The cor. of secs. 25, 30, 31, & 36, on the W. bdy. of the Tp., monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.
continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Cor. Sec. of 30, 31; 25, 36 T29-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of BTs mkd. by the Douglas County Surveyor's Office in 1952, reported by Moore and Browning

A decayed fir snag, size indeterminate, bears S.89½°E., 19.1 ft., with scribe marks 30 29 BT visible on bark of healed double blazes. (Record, S. 89½°W.)

A sawed, decayed fir stump, 26" dia. bears S.56°E., 71.9 ft. with scribe marks ST visible on bark.

and the remains of bearing trees mkd. by Rogers

A fir snag 16" dia bears N.79°E. 32.0 ft. with a healed blaze.

A fir 13" dia. bears S.27°W 244 ft., with a healed blaze.

A fir 18" dia. bears N.63°W. 38.3 ft. with a healed blaze.

and a bearing tree mkd by Moore and Browning

A fir 15" dia. bears S.77°E., 48.8 ft. with scribe marks T29S R6W S31 BT visible on a partially healed blaze.

and a new bearing tree

A fir 15" dia. bears N.72°E. 17.2 ft. mkd. T29S R6W S30 BT
Corner is located S 1 ft. from a wood fence post at the cor. of woven wire fences extending N and W., on a gradual N slope.

Latitude: 43°00'48.89"N., Longitude: 123°27'52.85"W.
NAD 1983 (CORS))