

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Fred Mensch under Contract #757 dated Sept. 14, 1904 (DCSO records Vol. 15 Page(s) 6496)

A Red Fir, 8" dia., for 1/4 cor. I marked 1/4 S29 on N. and 32 on S. side, from which

A Chinquapin 16" dia., bears N.16°W., 56 lks. dist., mkd. 1/4 S29 BT.

A Cedar 7" dia., bears S.55°W., 40 lks. dist., marked 1/4 S32 BT.

Survey by John Markham, Jr. - For: Stomar Lumber Co. - Aug/Oct 1956 - C.S. File 42/190-2

Point for corner determined by O.B.T.

A 20" Cedar bears S.55°W., 26.4 ft. dist.

At point for corner, Set 1 1/2" truck axle with flange up. from which

An 11" Chip. bears S.51°E., 15.0 ft. mkd. 1/4 S32 BT.

A 7" Laurel bears S.26°W., 32.0 ft. mkd. 1/4 S32 T29S R6W BT 2880.

A 40" Fir bears N.78°E., 60.0 ft. mkd. 1/4 S29 BT.

Road bears East, 108.0 ft. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Dale McFarland, John Powell, crew - March/April 1962 - C.S. File 49/139-40

Found - All BTs as recorded by Markham in 1956, but do not find axle set for corner.

Set Brass cap at cor. mkd: County Surveyors Office

T 29 S R 6 W

1/4 S 29
S 32

1962

No new bearing trees.

Fd. OK, by Burton Holt, March 1987, M 104-3

DCSO-GIS Corner visitation - 8/12/2004 - Typed: 2/1/2011 - C.S. File 67/33-1

Monument - 1 1/4" BC/IP

Comment - (needs) rehab

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - March 1, 2011 - C.S. File 67/33-19

Found - No evidence of 1956 axle monument found.
1962 2½" dia., brass cap on a 1½" ID iron pipe is firmly set & protrudes approx. 1 ft above ground.
Cap mkd: COUNTY SURVEYORS OFFICE

¼ ~~S29~~ S28
S32
1962

1904 Cedar, 7" dia., now a very rotted 20" dia., 1 ft tall cedar stump with no marks bears S.55°W., 26.4 ft. (as per rec.)

1956 11" chip. now a 22" DBH Chinquapin with a fully healed double blaze; bears S.48½°E., 15.7 ft. (rec. S.51°E., 15.0 ft., this is possibly a face measurement)

1956 7" laurel, now a 2 ft. tall 12" dia., madrone stump with a fully healed low blaze (we do not open); bears S.26°W., 32.0 ft. (as per rec)

1956 40" Fir now a 48" DBH D.Fir with a fully healed single blaze; bears N.78°E., 60.0 ft (As per rec)

New - A 22" DBH G.Fir scribed "¼ S29 CS" "BT" on a double blaze; bears N.17½°W., 42.1 ft.

A 15" DBH R.Cedar scribed "¼ S32 CS" "BT" on a double blaze; bears S.1½°E., 48.6 ft.

A 1½" dia., rebar with a 2" alum. cap is firmly set protruding 6" above ground and bears N.77°E., 56.5 ft. Mkd: 2010 OR-10-287



3500 BLM

Note - Monument is on flat forested bench west and north approx. 100 ft. from a dirt road.
Decl. 15¾°E

BLM Retracement by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2300, Surveyed Aug./Sept. 2009 - (DCS0 records Vol. 56 Page(s) 22275-6 & Plat T29-6 2011)

The ¼ sec. cor. of secs. 9 & 32, established by Mensch in 1905, perpetuated by Markham, in 1956, subsequently perpetuated by Byron, in 1962, monumented with an iron post, 1¼" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd.

continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of on orig. BT
A sawed, decayed cedar stump. size indeterminate, bears
S.55°W., 26.4 ft., with no marks visible.
and the remains of bearing trees mkd. by Markham
A fir, 47" dia., bears N.78¼°E., 59.7 ft., with no marks
visible on bark blaze.
A chinquapin, 22" dia., bears S.48¾°E., 15.4 ft., with
healed double blaze.
A sawed madrone stump, 12" dia., bears S.26¼°W., 32.2 ft.
with no marks visible.